





### General information

| Make                | AUDI                   |
|---------------------|------------------------|
| Model               | A4 TDI S LINE          |
| Colour              | Grey                   |
| Year of manufacture | 2009                   |
| Top speed           | 133 mph                |
| 0 - 60 mph          | 9.2 seconds            |
| Gearbox             | 6 speed Semi-Automatic |

## Engine & fuel consumption

| Power                   | 188 BHP             |
|-------------------------|---------------------|
| Max. torque             | 320 Nm at 2.500 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 36.7 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 47.9 mpg            |
| CO2 emission            | 143 g/km            |
| CO2 label               | F                   |







# Internet history

Entry 1

Date

2021-06-09

7

Pictures

Listing price

View report



source: autotrader.co.uk



# MOT history

| MOT expiry date    | 2024-05-29 |
|--------------------|------------|
| MOT pass rate      | 70 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 6          |
| Total advice items | 30         |
| Total items failed | 10         |

| MOT #20   | 2023-05-30 15:01 |
|---|------------------|
| MOT test number   | 601409175081     |
| Result  | 🗸 Passed         |
| Next expiry date  | 2024-05-29       |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice Slight corrosion to rear suspension components                             |                  |
| Advice Slight corrosion to both rear inner sills                                  |                  |

# MOT #19

| Result  | 🗙 Failed |
|---|----------|
| Advice Slight corrosion to rear suspension components                             |          |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |          |
| Advice Slight corrosion to both rear inner sills                                  |          |
| Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))                  |          |

| MOT #18   | 2022-04-08 07:33 |
|---|------------------|
| MOT test number   | 921523440820     |
| Result  | ✓ Passed         |
| Advice Tyre worn close to legal limit/worn on edge all wearing on edges (5.2.3 (e)) |                  |

2023-05-24 12:50 522080848874



| DY09NZZ                 |
|-------------------------|
| report date: 2024-03-29 |

| MOT #17  | 2022-04-07 08:02 |
|--|------------------|
| MOT test number  | 593741666531     |
| Result   | 🗙 Failed         |
| Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |                  |
| <b>Fail</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))             |                  |
| Advice Tyre worn close to legal limit/worn on edge all wearing on edges (5.2.3 (e))  |                  |
| <b>Fail</b> Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))            |                  |

| MOT #16  |  | 2021-06-09 10:31 |
|----------|--|------------------|
| MOT test | number   | 903952448341     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice   | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |                  |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |

| MOT #15  |  | 2020-07-03 15:23 |
|----------|--|------------------|
| MOT test | number   | 182784580896     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))             |                  |
| Advice   | Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))       |                  |
| Advice   | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                      |                  |
| Advice   | Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))      |                  |
| Advice   | Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) |                  |





| MOT #14     |  | 2020-07-03 09:53 |
|-------------|--|------------------|
| MOT test nu | ımber  | 228109896159     |
| Result      |  | 🗙 Failed         |
| Advice      | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                      |                  |
| Advice      | Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) |                  |
| Advice      | Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))             |                  |
| Advice      | Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))       |                  |
| Fail Offs   | ide Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))     |                  |
| Advice      | Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))      |                  |

| MOT #13         | 2019-07-11 16:05 |
|-----------------|------------------|
| MOT test number | 185961006985     |
| Result          | ✓ Passed         |

| MOT #12   | 2019-07-09 15:50 |  |
|---|------------------|--|
| MOT test number   | 348473272091     |  |
| Result  | 🗙 Failed         |  |
| Advice Nearside Rear Brake hose has slight corrosion to ferrule to caliper (1.1.12 (f) (i))     | )                |  |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e)) |                  |  |
| Fail   Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))  |                  |  |
| Advice Offside Rear Brake hose has slight corrosion to ferrule to caliper (1.1.12 (f) (i))      |                  |  |

| MOT #11         | 2019-01-03 15:36 |
|-----------------|------------------|
| MOT test number | 966440525104     |
| Result          | ✓ Passed         |





| MOT #10   | 2018-01-11 17:33 |
|---|------------------|
| MOT test number   | 845738532753     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #9  | 2017-04-15 13:45 |
| MOT test number   | 677134743532     |
| Result  | ✓ Passed         |
| Advice Rear Brake pad(s) wearing thin (3.5.1g)                    |                  |
|   |                  |
|   |                  |
| MOT #8  | 2017-01-18 11:15 |
| MOT test number   | 874404571790     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #7  | 2016-01-19 13:52 |
| MOT test number   | 767497264242     |
| Result  | ✓ Passed         |
|   |                  |
| МОТ #6  | 2015-03-20 11:17 |
| MOT test number   | 337639275094     |
| Result  | ✓ Passed         |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) |                  |
| Advice Rear Tyre worn close to the legal limit (4.1.E.1)          |                  |





| MOT #5  | 2015-03-19 12:54 |
|---|------------------|
| MOT test number   | 177268075085     |
| Result  | 🗙 Failed         |
| Fail   Offside front brake binding (3.7.B.1)                                      |                  |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)                 |                  |
| FailOffside Rear coil spring broken (2.4.C.1a)                                    |                  |
| Advice Rear Tyre worn close to the legal limit (4.1.E.1)                          |                  |
| <b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |                  |
|   |                  |
| MOT #4  | 2014-03-11 13:57 |
| MOT test number   | 359240374023     |

Result

| МОТ #3          | 2013-03-11 14:09 |
|-----------------|------------------|
| MOT test number | 846190473068     |
| Result          | ✓ Passed         |

| MOT #2  | 2013-03-11 12:43 |
|---|------------------|
| MOT test number   | 479770173054     |
| Result  | 🗙 Failed         |
| Fail   Centre Exhaust system not adequately supported (7.1.1) |                  |

| MOT #1  | 2012-03-09 09:18 |
|---|------------------|
| MOT test number   | 938769262097     |
| Result  | ✓ Passed         |
| Advice Front Tyre worn close to the legal limit (4.1.E.1) |                  |

🗸 Passed



Tax & MOT check

|                  | √<br>xed | <b>Expires:</b><br>29 May 2024 | ✓<br>МОТ           |
|------------------|----------|--------------------------------|--------------------|
| Tax status       |          |                                | Valid until 1 June |
| Days left        |          |                                | 33                 |
| MOT expiry date  |          |                                | 29 May 2024        |
| Full MOT history |          |                                | See MOT history    |

# Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |      |
|----------|------|
| Date     |      |
| Category | Lamp |
| Туре     |      |
| Damage 2 | AMPL |
| Date     |      |
| Date     | OLE  |
| Category | E.S. |
| Туре     |      |

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx  |             |
|---|-------------|
| **********  |             |
| ********  |             |
| *******   |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this AUDI had different number plates. |             |
| Number of plates  | 7           |
| Carrent registration  |             |
| Plate since   |             |
| Carrent registration  |             |
| Plate since   |             |
|   |             |





### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 22         |
| First mileage registration | 2009-03-12 |
| Last registration          | 2023-05-30 |
| Complete history           | See info   |



| Registration #1  | 2009-03-12 | 20 mi   |
|--|------------|---|
| Registration #2  | 2012-03-09 | 27.610 mi   |
| Registration #3  | 2013-03-11 | 30.387 mi   |
| Registration #4  | 2013-03-11 | 30.387 mi   |
| Registration #5  | 2014-03-11 | 37.199 mi   |
| Registration #6  | 2015-03-19 | 42.866 mi   |
| Registration #7  | 2015-03-20 | 42.866 mi   |
| Registration #8  | 2016-01-19 | 48.917 mi   |
| Registration #9  | 2017-01-18 | 53.044 mi   |
| Registration #10   | 2017-04-15 | 53.891 mi   |
| Registration #11   | 2018-01-11 | 58.034 mi   |
| Registration #12   |            | 11.777 es   |
|  |            |   |
| Registration #13   |            | 11. JUL 46  |
| Registration #13<br>Registration #14   |            | 11.777 es   |
|  |            | 01,000 est<br>01,000 est<br>01,000 est  |
| Registration #14   |            | 01,000 est<br>01,000 est<br>01,000 est<br>01,000 est  |
| Registration #14<br>Registration #15   |            | 01,000 est<br>01,000 est<br>01,000 est<br>01,000 est<br>01,000 est                                    |
| Registration #14<br>Registration #15<br>Registration #16   |            | 00.000 est<br>0.000 est<br>0.000 est<br>0.000 est<br>0.000 est<br>0.000 est                           |
| Registration #14<br>Registration #15<br>Registration #16<br>Registration #17   |            | 00,000 e8<br>0,000 e8<br>0,000 e8<br>0,000 e8<br>0,000 e8<br>0,000 e8<br>0,000 e8                     |
| Registration #14<br>Registration #15<br>Registration #16<br>Registration #17<br>Registration #18                     |            | 00.000 est<br>0.000 est<br>0.000 est<br>0.000 est<br>0.000 est<br>0.000 est<br>0.000 est<br>0.000 est |
| Registration #14<br>Registration #15<br>Registration #16<br>Registration #17<br>Registration #18<br>Registration #19 |            | 10,000 46<br>0,000 46<br>0,000 46<br>0,000 46<br>0,000 46<br>0,000 46<br>0,000 46<br>0,000 46         |





### Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| 50482  |                  |
| \$0501 |                  |
| S0566  |                  |
| \$0567 |                  |
| S0569  |                  |

# Safety ratings

**NCAP** rating

Video

see crash video



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1765 mm          |
| Height                            | 1423 mm          |
| Length                            | 4286 mm          |
| Wheel base                        | 2578 mm          |
| Kerb weight                       | 1385 kg          |
| Max. allowed weight               | 1945 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 55 I             |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 14/14     |

| Number of axles | 2         |
|-----------------|-----------|
| Engine number   | CBA505749 |