



DU59EWF

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-07-29
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	18
Total items failed	13

MOT #16	2023-11-17 09:32
MOT test number	965049822607
Result	✓ Passed
Next expiry date	2024-11-16
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2022-10-15 09:47
MOT test number	474048368240
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**MOT #14** 2022-10-08 10:42**MOT test number** 326533898377**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Fail** Offside Rear Suspension arm pin or bush likely to become detached trailing arm bush chalked (5.3.4 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge bold (5.2.3 (e))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13** 2021-06-01 08:31**MOT test number** 745179885743**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2020-09-03 11:44**MOT test number** 725332216876**Result** ✓ Passed**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #11**

2020-09-03 08:19

MOT test number

798974826871

Result**✗ Failed**

Fail Parking brake lever has excessive movement indicating incorrect adjustment Excessive travel (1.1.6 (c))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Rear Brake cable damaged Broken at caliper (1.1.15 (a))

MOT #10

2019-07-31 14:45

MOT test number

264670063282

Result**✓ Passed****MOT #9**

2019-07-26 13:25

MOT test number

268815456926

Result**✗ Failed**

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt Link rod (5.3.4 (b) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm Plus cut to cords (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #8

2018-08-09 14:54

MOT test number

664924865660

Result**✓ Passed**

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-08-09 11:21**MOT test number** 639451250599**Result** ✗ Failed**Fail** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit 1.73 av (8.2.2.2 (a))**MOT #6** 2017-08-07 08:51**MOT test number** 870155908847**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-07-11 09:43**MOT test number** 471898232521**Result** ✓ Passed**MOT #4** 2015-08-10 11:48**MOT test number** 185322025271**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2014-07-24 12:49**MOT test number** 158505204215**Result** ✓ Passed



MOT #2	2013-07-29 10:23
MOT test number	137620613261
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-07-26 13:44
MOT test number	995218902209
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 November 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	DU59EWF
Plate since	2019-03-28
Current registration	DU59EWF
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-01
Last registration	2023-11-17
Complete history	See info



Registration #1	2009-09-01	8 mi
Registration #2	2012-07-26	28.166 mi
Registration #3	2013-07-29	31.688 mi
Registration #4	2014-07-24	36.393 mi
Registration #5	2015-08-10	41.343 mi
Registration #6	2016-07-11	47.087 mi
Registration #7	2017-08-07	53.345 mi
Registration #8	2018-08-09	59.071 mi
Registration #9	2018-08-09	59.071 mi
Registration #10	2019-08-09	65.071 mi
Registration #11	2020-08-09	71.071 mi
Registration #12	2021-08-09	77.071 mi
Registration #13	2022-08-09	83.071 mi
Registration #14	2023-08-09	89.071 mi
Registration #15	2024-08-09	95.071 mi
Registration #16	2025-08-09	101.071 mi
Registration #17	2026-08-09	107.071 mi
Registration #18	2027-08-09	113.071 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9B03425