



**YF640PY**

report date: 2024-03-29

General information

Make	BMW
Model	225 320D M SPORT TOURING
Colour	White
Year of manufacture	2014
Top speed	141 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-10-20
Pictures	27
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-20
Pictures	27
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-09
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	7
Total items failed	7

MOT #11	2023-10-06 09:32
MOT test number	321257280860
Result	✓ Passed
Next expiry date	2024-10-09
Advice	Offside Front Suspension arm ball joint has slight play rear arm (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front thrust arm (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front thrust arm (5.3.4 (a) (i))

MOT #10	2022-10-10 09:03
MOT test number	331709230909
Result	✓ Passed

**MOT #9** 2022-10-05 14:24**MOT test number** 401232239424**Result** ✗ Failed

- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Nearside Front Nail in tyre
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2021-07-03 11:28**MOT test number** 394130039204**Result** ✓ Passed**MOT #7** 2020-07-08 12:00**MOT test number** 857578255398**Result** ✓ Passed**MOT #6** 2020-07-08 08:52**MOT test number** 570743185411**Result** ✗ Failed

- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #5** 2019-05-14 10:50**MOT test number** 970618679346**Result** ✓ Passed

**MOT #4** 2018-11-21 09:38**MOT test number** 797491205170**Result** ✓ Passed**MOT #3** 2018-11-16 13:24**MOT test number** 350360943324**Result** ✗ Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #2** 2017-11-20 14:16**MOT test number** 338035798903**Result** ✓ Passed

**Advice** Both front tyre outer edges devoid of tread

**MOT #1** 2017-11-20 09:21**MOT test number** 717619387452**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner sidewall (4.1.D.1b)

**Advice** Both front tyre outer edges devoid of tread



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
9 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	9 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-24
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2014-11-24	23 mi
Registration #2	2017-11-20	28.713 mi
Registration #3	2017-11-20	28.713 mi
Registration #4	2018-11-16	37.700 mi
Registration #5	2018-11-21	37.827 mi
Registration #6	2019-05-14	38.950 mi
Registration #7	2020-07-08	53.913 mi
Registration #8	2020-05-20	55.277 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1811 mm
Height	1462 mm
Length	4624 mm
Wheel base	2810 mm
Kerb weight	1500 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	81809040