



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Silver
Year of manufacture	2011
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-09-09
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-12
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-12
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	41
Total items failed	2

MOT #162024-02-13 13:03

MOT test number107965522049

Result✓ Passed

Next expiry date2025-02-12

- Advice Brake pedal wearing smooth (1.1.2 (c))
- Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Minor Windscreen damaged but not adversely affecting driver's view Chip (3.2 (a) (i))
- Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice Oil leak, but not excessive From round injectors (8.4.1 (a) (i))
- Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15** 2023-01-24 16:00**MOT test number** 119650864875**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view Chip (3.2 (a) (i))

MOT #14 2023-01-17 14:22**MOT test number** 948152079946**Result** ✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Nearside Front Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view Chip (3.2 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2021-10-18 14:13**MOT test number** 154421164350**Result** ✓ Passed

**MOT #12** 2021-05-10 17:43**MOT test number** 918508217199**Result** ✓ Passed**MOT #11** 2021-05-08 15:53**MOT test number** 789852748671**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2020-12-22 13:54**MOT test number** 387591972814**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9** 2020-12-19 08:42**MOT test number** 497494576968**Result** ✗ Failed**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #8** 2019-12-12 08:39**MOT test number** 738955445927**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-12-22 11:16**MOT test number** 439608519094**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2018-12-22 11:16**MOT test number** 971325926886**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2017-12-23 08:43**MOT test number** 245050343938**Result** ✓ Passed**Advice** Perishing to both rear tyre tread areas**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-12-23 08:43**MOT test number** 346366543820**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Perishing to both rear tyre tread areas



MOT #3	2016-12-17 08:52
MOT test number	476189927995
Result	✓ Passed
Advice	Under trays fitted
Advice	BOTH front brake discs lipped
Advice	BOTH rear tyre treads perished and cracked

MOT #2	2015-12-05 12:16
MOT test number	328702476872
Result	✓ Passed

MOT #1	2014-12-20 11:08
MOT test number	518404154318
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
12 February 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-12-22
Last registration	2024-02-13
Complete history	See info



Registration #1	2011-12-22	24 mi
Registration #2	2014-12-20	23.406 mi
Registration #3	2015-12-05	32.173 mi
Registration #4	2016-12-17	41.032 mi
Registration #5	2017-12-23	50.326 mi
Registration #6	2017-12-23	50.326 mi
Registration #7	2018-12-22	58.687 mi
Registration #8	2018-12-22	58.687 mi
Registration #9	2019-12-12	67.559 mi
Registration #10	2020-12-19	72.891 mi
Registration #11	2020-12-22	72.891 mi
Registration #12	2020-12-22	72.891 mi
Registration #13	2020-12-22	72.891 mi
Registration #14	2020-12-22	72.891 mi
Registration #15	2020-12-22	72.891 mi
Registration #16	2020-12-22	72.891 mi
Registration #17	2020-12-22	72.891 mi
Registration #18	2020-12-22	72.891 mi
Registration #19	2020-12-22	72.891 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number D4FDBZ019926