



General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Blue
Year of manufacture	2008
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	20
Total items failed	9

MOT #20	2024-01-16 14:06
MOT test number	540627442202
Result	✓ Passed
Next expiry date	2025-01-16

MOT #19	2024-01-15 13:11
MOT test number	917444595574
Result	✗ Failed
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #18	2023-01-17 13:14
MOT test number	257333220139
Result	✓ Passed
Advice	Nearside rear view mirror slightly insecure

MOT #17	2023-01-17 10:43
MOT test number	582633471999
Result	✗ Failed
Fail	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Nearside rear view mirror slightly insecure
Fail	Front Windscreen washer not working both (3.5 (a))

**MOT #16** 2022-01-14 11:37**MOT test number** 871091655604**Result** ✓ Passed**MOT #15** 2020-08-05 14:49**MOT test number** 835431526601**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))**MOT #14** 2020-08-05 14:49**MOT test number** 762184958855**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #13** 2019-08-01 15:26**MOT test number** 401135388476**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2019-08-01 11:18**MOT test number** 652057816000**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire (6.1.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-07-12 15:36**MOT test number** 488972721556**Result** ✓ Passed**MOT #10** 2017-07-26 09:40**MOT test number** 235929109530**Result** ✓ Passed**MOT #9** 2016-07-27 09:44**MOT test number** 819146220405**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-07-27 09:44**MOT test number** 846517921744**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #7** 2015-07-23 10:25**MOT test number** 505384505258**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-07-22 13:44**MOT test number** 409113304283**Result** ✓ Passed**MOT #5** 2014-07-22 13:44**MOT test number** 375153904290**Result** ✗ Failed**Pass with rectification** Horn not working (1.6.2a)**MOT #4** 2013-07-23 11:41**MOT test number** 396544203280**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-07-18 13:44**MOT test number** 749600102289**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-07-05 15:01**MOT test number** 949866481117**Result** ✓ Passed



MOT #1	2011-07-04 14:30
MOT test number	248865781447
Result	✗ Failed
Fail	Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-31
Last registration	2024-01-16
Complete history	See info



Registration #1	2008-07-31	9 mi
Registration #2	2011-07-04	12.268 mi
Registration #3	2011-07-05	12.268 mi
Registration #4	2012-07-18	18.737 mi
Registration #5	2013-07-23	24.086 mi
Registration #6	2014-07-22	29.978 mi
Registration #7	2015-07-23	35.252 mi
Registration #8	2016-07-27	40.283 mi
Registration #9	2016-07-27	40.283 mi
Registration #10	2017-07-26	44.353 mi
Registration #11	2018-07-12	47.875 mi
Registration #12	2019-01-20	51.397 mi
Registration #13	2019-01-20	54.919 mi
Registration #14	2019-01-20	58.441 mi
Registration #15	2019-01-20	61.963 mi
Registration #16	2019-01-20	65.485 mi
Registration #17	2019-01-20	69.007 mi
Registration #18	2019-01-20	72.529 mi
Registration #19	2019-01-20	76.051 mi
Registration #20	2019-01-20	79.573 mi
Registration #21	2019-01-20	83.095 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8K23159