





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND PICASSO GRAND BLUEHDI FEEL S/S
Colour	Red
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-02
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #6	2024-01-03 14:10
MOT test number	600375193408
Result	✓ Passed
Next expiry date	2025-01-02
Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2024-01-03 14:10	
MOT test number	761373838660	
Result	× Failed	
Pass with rectification Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT test number

696032020297

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

MOT test number

879186946354

Result

MOT #2

2020-08-18 16:17

MOT test number

593488888816

Result

Advice Front Tyre slightly damaged/cracking or perishing *BOTH* (5.2.3 (d) (ii))

MOT test number

Result

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Front Tyre slightly damaged/cracking or perishing *BOTH* (5.2.3 (d) (ii))

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners have? Check it in the premium report and see all owner registrations. Download the full rep		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK CONTRACTOR	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



SO17FHK report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



SO17FHK report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-08-10
Last registration	2024-01-03
Complete history	See info



Registration #1	2017-08-10	11 mi
Registration #2	2020-08-18	23.168 mi
Registration #3	2020-08-18	23.168 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 9/10



SO17FHK report date: 2024-03-28

Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1826 mm
Height	1644 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1347 kg
Max. allowed weight	2175 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JCAN3042659

CarCheck.co.uk page 10/10