





### General information

Make	AUDI
Model	Q5 TDI QUATTRO SE
Colour	Blue
Year of manufacture	2017
Top speed	135 mph
0 - 100 km/h	7.9 seconds
0 - 60 mph	7.9 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	140 kW / 191 HP / 187 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E








### Internet history

Entry 1	
Date 2021-08-13	
Pictures 28	
Listing price <u>View report</u>	









source: yesauto.com



## MOT history

MOT expiry date	2024-08-08
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #6	2023-07-17 14:53
MOT test number	226263824179
Result	🗸 Passed
Next expiry date	2024-08-08
Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	

MOT #5	2022-08-09 12:00
MOT test number	471443417665
Result	✓ Passed
Advice Low emitter	

MOT #4	2021-08-09 17:47
MOT test number	963282268163
Result	✓ Passed

MOT #3	2021-02-18 17:12
MOT test number	293034196373
Result	✓ Passed
Advice Central Front Items removed from driver's view prior to test air freshe	ener
Minor Offside Rear Lower Direction indicator lens defective which has no effective (i))	ect on emitted light (4.4.1 (b)





MOT #2		2021-02-18 13:46
MOT test	number	322432231006
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm measure	ed (5.2.3 (e))
<b>MAJOR</b> (5.2.3 (d)	Nearside Rear Tyre has a cut in excess of the requirements deep enough t (i))	to reach the ply or cords
Advice	Offside Rear Nail in tyre	
Minor (i))	Offside Rear Lower Direction indicator lens defective which has no effect or	n emitted light (4.4.1 (b)
Advice	Central Front Items removed from driver's view prior to test air freshener	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm measur	red (5.2.3 (e))
<b>MAJOR</b> (5.2.3 (d)	Offside Rear Tyre has a cut in excess of the requirements deep enough to (i))	reach the ply or cords
Advice	Offside Rear Nail in tyre	
MOT #1		2020-03-17 09:16

MOT	test	number

Result

677345421997

🗸 Passed



Tax & MOT check

✓ Taxed	✓ MOT
<b>Tax due:</b> 1 August 2024	<b>Expires:</b> 8 August 2024
Tax status	Valid until 1 August
Days left	93
MOT expiry date	8 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Plate since Carrent registration	
Plate since Carrent registration Plate since	





#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-26
Last registration	2023-07-17
Complete history	See info



Registration #1	2017-05-26	22 mi
Registration #2	2020-03-17	49.192 mi
Registration #3	2021-02-18	56.826 mi
Registration #4	2021-02-18	56.826 mi
Registration #5		11.177 mi
Registration #6		11.117 esi
Registration #7		11.777 mi
Registration #8		11.777 mi





## Car features

S0225	Air conditioning
\$0295	
50482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	73%
Safety systems	58%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	2140 mm
Height	1659 mm
Length	4663 mm
Wheel base	2819 mm
Kerb weight	1745 kg
Additional information	
Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	DETA094358 page 11/11