



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Gold
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 3



Date	2022-05-18
Pictures	47
Listing price	View report



source: yesauto.com

Entry 2

Date	2022-03-30
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-18
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	8
Total items failed	7

MOT #17	2023-11-01 09:35
MOT test number	649143147555
Result	✓ Passed
Next expiry date	2024-10-31

MOT #16	2023-01-03 09:45
MOT test number	229245629441
Result	✓ Passed

MOT #15	2022-04-07 16:10
MOT test number	397024403259
Result	✓ Passed

MOT #14	2022-02-11 14:54
MOT test number	253904043817
Result	✓ Passed

MOT #13	2022-02-03 10:17
MOT test number	805568790866
Result	✗ Failed

MAJOR Anti-lock braking system warning lamp does not illuminate (1.6 (a))

MAJOR Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #12** 2020-12-21 09:20**MOT test number** 779588263115**Result** ✓ Passed**MOT #11** 2019-11-29 10:48**MOT test number** 260672835425**Result** ✓ Passed**MOT #10** 2018-10-15 11:39**MOT test number** 582786889508**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #9** 2018-10-15 09:35**MOT test number** 880340382253**Result** ✗ Failed**MAJOR** Nearside Front Side repeater not working Unit in mirror broken (4.4.1 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MAJOR** Nearside Front Outline marker lamp not working (4.2.1 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #8** 2017-09-15 14:43**MOT test number** 367739402683**Result** ✓ Passed

**MOT #7** 2017-09-13 13:32**MOT test number** 250086844665**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2016-09-14 14:22**MOT test number** 316645437544**Result** ✓ Passed**MOT #5** 2016-09-14 14:22**MOT test number** 371570134948**Result** ✗ Failed**Pass with rectification** Nearside Side repeater incorrect colour (1.4.A.2f)**MOT #4** 2015-09-21 12:21**MOT test number** 409769500934**Result** ✓ Passed**MOT #3** 2014-10-23 12:55**MOT test number** 748236794286**Result** ✓ Passed**MOT #2** 2014-10-23 12:55**MOT test number** 845246694286**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #1	2013-10-09 10:31
MOT test number	846492183267
Result	✓ Passed



Tax & MOT check

✖
Untaxed

Tax expired:
28 January 2023

✓
MOT

Expires:
31 October 2024

Tax status	Expired at 28 January 2023
Days left	457 days too late
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-11-30
Last registration	2023-11-01
Complete history	See info



Registration #1	2010-11-30	21 mi
Registration #2	2013-10-09	31.593 mi
Registration #3	2014-10-23	38.118 mi
Registration #4	2015-09-21	42.698 mi
Registration #5	2016-09-14	49.402 mi
Registration #6	2016-09-14	49.402 mi
Registration #7	2017-09-13	59.058 mi
Registration #8	2017-09-15	59.069 mi
Registration #9	2018-10-15	63.522 mi
Registration #10	2018-10-15	63.522 mi
Registration #11	2019-05-20	65.557 mi
Registration #12	2019-05-20	65.557 mi
Registration #13	2019-05-20	65.557 mi
Registration #14	2019-05-20	65.557 mi
Registration #15	2019-05-20	65.557 mi
Registration #16	2019-05-20	65.557 mi
Registration #17	2019-05-20	65.557 mi
Registration #18	2019-05-20	65.557 mi
Registration #19	2019-05-20	65.557 mi
Registration #20	2019-05-20	65.557 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	848865