





### General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Silver
Year of manufacture	2012
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D







# Internet history

Entry	1
Date	


2021-09-21

Pictures

Listing price

View report

34



source: autotrader.co.uk



### MOT history

MOT expiry date	2024-10-25
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	12
Total items failed	1

MOT #11	2023-10-05 09:19
MOT test number	983936334844
Result	✓ Passed
Next expiry date	2024-10-25
<b>Minor</b> Offside Rear Position lamp with a multiple light source up to 1/2 not not showing white to rear at time of test (4.2.1 (a) (i))	functioning Also lens damaged,

MOT #10	2022-10-26 11:18
MOT test number	240256972124
Result	✓ Passed
МОТ #9	2021-10-05 14:02
MOT test number	949266191962

FIOT test number	545200151502
Result	✓ Passed

MOT #8	2020-10-19 08:58
MOT test number	947280179124
Result	✓ Passed

MOT #7	2019-10-14 15:16
MOT test number	814415170234
Result	✓ Passed
Advice Under body covers fitted	





MOT #6	2019-10-14 08:25
MOT test number	451734738776
Result	🗙 Failed
<ul> <li>DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</li> <li>Advice Under body covers fitted</li> <li>Advice Offside Front Tyre very close to legal limit</li> </ul>	
Advice Offside Front Tyre very close to legal limit	

MOT #5		2018-10-22 12:37
MOT test	number	532546305148
Result		✓ Passed
Advice	O/s/f tyre creaking on rotation	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2017-10-18 12:26
MOT test number	499178346472
Result	✓ Passed

MOT #3		2017-10-17 08:59
MOT test	number	984252338813
Result		🗙 Failed
Fail B	rake fluid warning lamp illuminated (3.6.G.2)	
Advice	Rear tyres nsr + osr have heavily stepped on inner tread sections attention nee	eded
Advice	Rear Brake pad(s) wearing thin brake pad warning lamp on attention needed (3	3.5.1g)
Advice	Front Brake pad(s) wearing thin pad warning lamp on attention needed (3.5.1g	)





MOT #2		2016-08-03 08:10
MOT test	number	144875414884
Result		✓ Passed
Advice	Nearside Rear Inner tread worn to saw tooth pattern	
Advice	Offside Rear Inner tread worn to saw tooth pattern	

MOT #1	2015-07-01 16:14
MOT test number	378622485159
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	MOT Expires: 25 October 2024
Tax status	Valid until 1 October
Days left	156
MOT expiry date	25 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-21
Last registration	2023-10-05
Complete history	<u>See info</u>



Registration #1	2012-07-21	20 mi
Registration #2	2015-07-01	32.892 mi
Registration #3	2016-08-03	35.335 mi
Registration #4	2017-10-17	40.081 mi
Registration #5	2017-10-18	40.086 mi
Registration #6	2018-10-22	45.551 mi
Registration #7	2019-10-14	49.462 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		





# Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12