



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO 625 LX L1 HDI
Colour	Silver
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	16.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	185 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2021-01-29
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	10
Total items failed	21

MOT #15	2020-01-15 09:19
MOT test number	819458851791
Result	✓ Passed
Next expiry date	2021-01-29

MOT #14	2019-01-30 17:14
MOT test number	804305138596
Result	✓ Passed

MOT #13	2019-01-30 16:37
MOT test number	445640472800

Result	✗ Failed
--------	----------

- Fail** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Central Stop lamp(s) not working high level (4.3.1 (a) (ii))

MOT #12	2018-04-10 10:56
MOT test number	386515156815
Result	✓ Passed



MOT #11	2018-04-09 14:28
MOT test number	162225267681
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Fail	Offside Front front brake excessively fluctuating (3.7.B.3)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front front brake excessively fluctuating (3.7.B.3)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #10	2017-07-11 10:29
MOT test number	241759577298
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)
Advice	Rear tyres cracking

**MOT #9** 2017-07-10 16:19**MOT test number** 697924797323**Result** ✗ Failed**Advice** Rear tyres cracking**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**MOT #8** 2016-07-19 14:26**MOT test number** 550703348942**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-06-30 15:11**MOT test number** 489081485113**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-07-03 09:12**MOT test number** 338974884107**Result** ✓ Passed

**MOT #5** 2014-07-03 09:12**MOT test number** 546974184116**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2013-06-18 09:13**MOT test number** 745349563114**Result** ✓ Passed**MOT #3** 2013-06-18 09:13**MOT test number** 549199063107**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2012-11-19 15:03**MOT test number** 788834022383**Result** ✓ Passed**MOT #1** 2012-11-19 15:03**MOT test number** 799934322372**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✕
Untaxed

Tax expired:
7 January 2021

✕
MOT

Expired:
29 January 2021

Tax status	Expired at 7 January 2021
Days left	1209 days too late
MOT expiry date	29 January 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-10-08
Last registration	2020-01-15
Complete history	See info



Registration #1	2009-10-08	22 mi
Registration #2	2012-11-19	36.321 mi
Registration #3	2013-06-18	45.775 mi
Registration #4	2014-07-03	68.537 mi
Registration #5	2015-06-30	84.695 mi
Registration #6	2016-07-19	95.406 mi
Registration #7	2017-07-10	96.144 mi
Registration #8	2018-06-20	96.277 mi
Registration #9	2019-06-20	96.277 mi
Registration #10	2019-06-20	96.277 mi
Registration #11	2019-06-20	96.277 mi
Registration #12	2019-06-20	96.277 mi
Registration #13	2019-06-20	96.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2112 mm
Height	1834 mm
Length	4380 mm
Kerb weight	1354 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBCB0054539