



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Grey
Year of manufacture	2012
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-02
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-14
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	29
Total items failed	8

MOT #14 2023-06-14 15:18

MOT test number 926567992658

Result ✓ Passed

Next expiry date 2024-06-14

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Emissions too low to record
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13 2022-06-15 12:46

MOT test number 351096041573

Result ✓ Passed

MOT #12 2021-08-05 08:24

MOT test number 718044607070

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-02-18 11:03**MOT test number** 618188820338**Result** ✓ Passed**MOT #10** 2020-02-18 15:38**MOT test number** 377243360920**Result** ✓ Passed**MOT #9** 2020-02-17 09:12**MOT test number** 857036414086**Result** ✗ Failed

Fail Offside Rear Suspension component pin or bush excessively worn trailing arm large front bush (5.3.4 (a) (i))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))

Fail Nearside Rear Suspension component pin or bush excessively worn trailing arm large front bush (5.3.4 (a) (i))

Fail Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #8 2019-03-16 13:46**MOT test number** 769557040575**Result** ✓ Passed

**MOT #7**

2019-01-09 09:37

MOT test number

698135563147

Result

✗ Failed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #6

2018-01-09 09:42

MOT test number

762731905107

Result

✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5

2017-01-20 09:43

MOT test number

130996380328

Result

✓ Passed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2017-01-17 09:43**MOT test number** 980624130892**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2016-01-14 09:25**MOT test number** 667936213274**Result** ✓ Passed**Advice** Nearside Rear Inner Road wheel slightly damaged (4.2.A.1a)**MOT #2** 2015-01-19 15:02**MOT test number** 377899415023**Result** ✓ Passed**MOT #1** 2015-01-19 15:02**MOT test number** 817339115000**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-01-25
Last registration	2023-06-14
Complete history	See info



Registration #1	2012-01-25	22 mi
Registration #2	2015-01-19	47.946 mi
Registration #3	2016-01-14	59.311 mi
Registration #4	2017-01-17	72.144 mi
Registration #5	2017-01-20	72.239 mi
Registration #6	2018-01-09	83.852 mi
Registration #7	2019-01-09	96.589 mi
Registration #8	2019-03-16	98.157 mi
Registration #9	2020-06-20	100,000
Registration #10	2020-06-20	100,000
Registration #11	2020-06-20	100,000
Registration #12	2020-06-20	100,000
Registration #13	2020-06-20	100,000
Registration #14	2020-06-20	100,000
Registration #15	2020-06-20	100,000

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1773 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1109863