



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI CDTI 16V
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	186 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-07-29
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-09-02
MOT pass rate	54 %
MOT passed	13
Failed MOT tests	11
Total advice items	72
Total items failed	25

MOT #24	2021-08-11 14:02
MOT test number	642699123376
Result	✓ Passed
Next expiry date	2022-09-02

MOT #23	2021-08-11 11:04
MOT test number	835094646034
Result	✗ Failed
Fail	Offside Rear Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))
Fail	Nearside Rear Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #22	2020-08-03 17:09
MOT test number	833176710875
Result	✓ Passed

**MOT #21**

2020-07-31 14:04

**MOT test number**

242757143306

**Result****✗ Failed**

**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Offside Front Headlamp insecure (4.1.1 (c))

**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Offside Headlamp aim too low (4.1.2 (a))

**MOT #20**

2019-09-03 14:43

**MOT test number**

619157280351

**Result****✓ Passed**

**Advice** Brake pipe corroded, covered in grease or other material Front to rear covered in grease (1.1.11 (c))

**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Rear Service brake fluctuating, but not excessively BOTH rears...also slightly felt through foot pedal (1.2.1 (e))

**Advice** Front Bumper damaged / cracked! NO sharp edges at time of test

**MOT #19**

2019-09-02 16:24

**MOT test number**

546795612319

**Result****✗ Failed****Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Brake pipe corroded, covered in grease or other material Front to rear covered in grease (1.1.11 (c))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Bumper damaged / cracked! NO sharp edges at time of test**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn REAR bush worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))**Advice** Rear Service brake fluctuating, but not excessively BOTH rears...also slightly felt through foot pedal (1.2.1 (e))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Direction indicator slightly discoloured BOTH rears (4.4.3 (a))**MOT #18**

2018-07-06 14:42

**MOT test number**

493679631381

**Result****✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge edges 235/35\*19 (5.2.3 (e))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm & edges 235/35\*19 (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))



MOT #17	2018-06-29 14:12
MOT test number	748610300928
Result	✗ Failed
Advice	Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm & edges 235/35*19 (5.2.3 (e))
Fail	Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge edges 235/35*19 (5.2.3 (e))

MOT #16	2017-06-24 09:59
MOT test number	555675094147
Result	✓ Passed
Advice	Rear Direction indicators slightly discoloured (1.4.A.2f)
Advice	Front tyres close to body on full lock
Advice	Offside Rear Brake pipe slightly corroded side of fuel tank (3.6.B.2c)
Advice	Engine bay/under body covers fitted

**MOT #15**

2017-06-23 13:56

**MOT test number**

655662598095

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Brake pipe slightly corroded side of fuel tank (3.6.B.2c)
- Advice** Road wheel with a slightly distorted bead rim all wheels (4.2.A.1a)
- Advice** Front tyres close to body on full lock
- Fail** Nearside Rear Road wheel cracked (4.2.A.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Battery insecure (1.9.1)
- Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Engine bay/under body covers fitted
- Fail** Offside Front Road wheel cracked (4.2.A.1a)

**MOT #14**

2016-07-01 11:06

**MOT test number**

463295199361

**Result****✓ Passed**

- Advice** Nearside Rear secondary brake light out
- Advice** Evidence of front tyres fouling chassis/body on full lock.
- Advice** Both rear tyres slightly out of shape on inside of tread pattern
- Advice** Offside Rear secondary brakelight out.

**MOT #13**

2016-06-30 15:16

**MOT test number**

284336642338

**Result****✗ Failed**

- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Stop lamp obviously incorrectly positioned one higher than the other due to blown bulbs (1.2.1a)
- Advice** Both rear tyres slightly out of shape on inside of tread pattern
- Advice** Offside Rear secondary brakelight out.
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Rear secondary brake light out
- Advice** Evidence of front tyres fouling chassis/body on full lock.
- Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure inner tread out of shape (4.1.D.1b)

**MOT #12**

2015-06-22 13:12

**MOT test number**

235683275104

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/s/r tyre cracked in tread pattern
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Notice** N/s/f tyre badly cracked in tread pattern
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)



**MOT #11**

2015-06-22 11:52

**MOT test number**

837703575131

**Result****✗ Failed**

- Notice** O/s/r tyre cracked in tread pattern
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Notice** N/s/f tyre badly cracked in tread pattern
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2014-06-02 14:28

**MOT test number**

718083354117

**Result****✓ Passed**

- Notice** Offside & nearside rear tyres cracking
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #9**

2014-06-02 11:12

**MOT test number**

476433454109

**Result****✗ Failed**

- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Notice** Offside & nearside rear tyres cracking
- Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)
- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #8** 2013-06-18 16:32**MOT test number** 796709763165**Result** ✓ Passed**MOT #7** 2013-02-07 17:46**MOT test number** 806338733069**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2013-02-07 10:08**MOT test number** 665528033080**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front coil spring fractured (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-01-23 12:34**MOT test number** 628413422019**Result** ✓ Passed

**MOT #4** 2011-01-31 14:13**MOT test number** 329161131067**Result** ✓ Passed**Notice** The amount of light admitted by tinting on front side windows does not form part of the test**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2011-01-31 14:13**MOT test number** 459201231098**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** The amount of light admitted by tinting on front side windows does not form part of the test**MOT #2** 2010-02-12 09:18**MOT test number** 183263040098**Result** ✓ Passed**MOT #1** 2010-02-09 17:22**MOT test number** 984480140015**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✕  
Untaxed

Tax expired:  
8 October 2021

✕  
MOT

Expired:  
2 September 2022

Tax status	Expired at 8 October 2021
Days left	933 days too late
MOT expiry date	2 September 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KH07YBR
Plate since	2019-09-29
Current registration	 KH07YBR
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-05-22
Last registration	2021-08-11
Complete history	<a href="#">See info</a>



Registration #1	2007-05-22	14 mi
Registration #2	2010-02-09	24.518 mi
Registration #3	2010-02-12	24.518 mi
Registration #4	2011-01-31	41.004 mi
Registration #5	2012-01-23	51.357 mi
Registration #6	2013-02-07	69.665 mi
Registration #7	2013-02-07	69.665 mi
Registration #8	2013-06-18	69.977 mi
Registration #9	2014-06-02	75.028 mi
Registration #10	2014-06-02	75.028 mi
Registration #11	2015-06-22	82.114 mi
Registration #12	2015-06-22	82.115 mi
Registration #13	2016-06-30	88.351 mi
Registration #14	2016-06-30	88.351 mi
Registration #15	2016-06-30	88.351 mi
Registration #16	2016-06-30	88.351 mi
Registration #17	2016-06-30	88.351 mi
Registration #18	2016-06-30	88.351 mi
Registration #19	2016-06-30	88.351 mi
Registration #20	2016-06-30	88.351 mi
Registration #21	2016-06-30	88.351 mi
Registration #22	2016-06-30	88.351 mi
Registration #23	2016-06-30	88.351 mi
Registration #24	2016-06-30	88.351 mi
Registration #25	2016-06-30	88.351 mi



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1501 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	17232764