





report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE BLUE DRIVE
Colour	Silver
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-08-05

Pictures 44

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-11-20
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	0

MOT #8		2023-11-06 15:37
MOT test n	number	910051899493
Result		✓ Passed
Next expir	y date	2024-11-20
Advice Offside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))		

MOT #7		2023-10-31 13:35
MOT test	number	229402167775
Result		X Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))		
MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))		
DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		

MOT #6	2022-11-21 14:30
MOT test number	623220675809
Result	✓ Passed
MOT #5	2022-05-20 11:58
MOT test number	937422343649
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4	2021-05-11 08:04
MOT test number	923155583076
Result	✓ Passed
MOT #3	2020-05-26 12:09
MOT test number	626218999785
Result	✓ Passed
MOT #2	2019-05-08 15:25
MOT test number	181792665290
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1		2019-05-08 11:58
MOT test	number	560436376011
Result		× Failed
MAJOR	Rear Registration plate does not conform to the specified requirements (0.1 (d))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Front Registration plate does not conform to the specified requirements (0.1 (d))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/11



EF16URG report date: 2024-03-29

Tax & MOT check





Expires: 20 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

EF16URG

report date: 2024-03-29

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-18
Last registration	2023-11-06
Complete history	See info



Registration #1	2016-05-18	26 mi
Registration #2	2019-05-08	29.549 mi
Registration #3	2019-05-08	29.549 mi
Registration #4	2020-05-26	37.536 mi
Registration #5	2021-05-11	42.159 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
•		11.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	2003 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	7	page 11/11

Number of axles 2

Engine number D4HBFU347475