



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 2

Date	2022-01-01
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-31
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-31
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	30
Total items failed	13

MOT #20 2024-02-01 11:17

MOT test number 950757551114

Result ✓ Passed

Next expiry date 2025-01-31

**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19 2023-01-27 10:43

MOT test number 439175725294

Result ✓ Passed

**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #18 2022-01-26 19:07

MOT test number 498895463347

Result ✓ Passed

MOT #17 2021-01-19 12:15

MOT test number 338271526555

Result ✓ Passed

**MOT #16**

2021-01-19 12:14

**MOT test number**

270942684682

**Result**

✗ Failed

**Pass with rectification**

Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Pass with rectification**

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**Pass with rectification**

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #15**

2020-01-26 15:27

**MOT test number**

792641505913

**Result**

✓ Passed

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2019-01-14 10:38

**MOT test number**

484708745867

**Result**

✓ Passed

**MOT #13**

2018-01-20 10:36

**MOT test number**

970070731370

**Result**

✓ Passed

**MOT #12** 2018-01-20 10:36**MOT test number** 716804179106**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Headlamp insecure (1.7.3)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2016-12-20 11:27**MOT test number** 975212996545**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear tyre has a nail**MOT #10** 2015-05-12 16:29**MOT test number** 378072435115**Result** ✓ Passed**Advice** Nearside Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #9** 2014-05-21 09:33**MOT test number** 865421344124**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2014-05-21 09:33**MOT test number** 908511044132**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #7** 2013-05-16 16:03**MOT test number** 325996733151**Result** ✓ Passed

**MOT #6** 2013-05-16 16:03**MOT test number** 676996333147**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2012-05-16 09:34**MOT test number** 509467432187**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-31 10:47**MOT test number** 106640791460**Result** ✓ Passed**MOT #3** 2011-03-30 11:08**MOT test number** 258529381058**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front discs slightly pitted**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2010-04-26 17:56**MOT test number** 392296710193**Result** ✓ Passed



MOT #1	2010-04-26 10:39
MOT test number	503166010141
Result	✗ Failed
Fail	Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
31 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	31 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-29
Current registration	XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-12-30
Last registration	2024-02-01
Complete history	<a href="#">See info</a>



Registration #1	2006-12-30	22 mi
Registration #2	2010-04-26	29.603 mi
Registration #3	2010-04-26	29.603 mi
Registration #4	2011-03-30	38.486 mi
Registration #5	2011-03-31	38.486 mi
Registration #6	2012-05-16	51.593 mi
Registration #7	2013-05-16	61.904 mi
Registration #8	2014-05-21	73.035 mi
Registration #9	2015-05-12	78.353 mi
Registration #10	2016-12-20	84.551 mi
Registration #11	2018-01-20	88.710 mi
Registration #12	2019-05-20	95.557 mi
Registration #13	2020-05-20	95.557 mi
Registration #14	2021-05-20	95.557 mi
Registration #15	2022-05-20	95.557 mi
Registration #16	2023-05-20	95.557 mi
Registration #17	2024-02-01	95.557 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	6U41344
---------------	---------