





General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | I800 CRDI SE |
| Colour | Silver |
| Year of manufacture | 2017 |
| Top speed | 104 mph |
| 0 - 60 mph | 17.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 343 Nm at 1.500 rpm |
| Engine capacity | 2.497 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 37.7 mpg |
| CO2 emission | 197 g/km |
| CO2 label | J |







Internet history

Entry 1

Date Pictures 2022-04-29

19

Listing price

View report







source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-02-04 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 2 |

| MOT #7 | 2024-02-02 15:39 |
|--|------------------|
| MOT test number | 181569659033 |
| Result | 🗸 Passed |
| Next expiry date 2025-02-04 | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| МОТ #6 | 2023-02-04 12:05 | |
|---|------------------|--|
| MOT test number | 581203133495 | |
| Result | ✓ Passed | |
| Advice Offside Child Seat fitted not allowing full inspection of adult belt centre row | | |
| Minor Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i)) | | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |



| MOT #5 | | 2023-02-04 12:05 |
|--|---|------------------------|
| MOT test number | | 438895172667 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Headlamp aim too high (4.1.2 (a)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice Offside Child Seat fitted not allowing full inspection of adult belt centre row | | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Minor Nearside Registra | ation plate lamp missing in the case of multiple lamps or lig | Jht sources (4.7.1 (b) |

| МОТ #4 | 2022-02-02 11:02 |
|---|---------------------------|
| MOT test number | 509335230488 |
| Result | ✓ Passed |
| AdviceOffside Front Lower Suspension arm pin or bush worn but not result rear bush (5.3.4 (a) (i))AdviceNearside Rear Nail in tyre | ing in excessive movement |

| МОТ #3 | | 2022-02-02 11:02 |
|---|--|------------------|
| MOT test number | | 451545916413 |
| Result | | 🗙 Failed |
| Advice Nearside Rear N | ail in tyre | |
| Pass with rectification | Offside Headlamp not working on dipped beam (4.1.1 (a) (ii |)) |
| Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) | | |

| MOT #2 | 2021-02-05 10:27 |
|-----------------|------------------|
| MOT test number | 385601533664 |
| Result | ✓ Passed |





| MOT #1 | 2020-02-05 16:49 |
|-----------------|------------------|
| MOT test number | 558692645811 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 August 2024 | ✓ MOT Expires: 4 February 2025 |
|---|---|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 4 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLI |
| | |
| Date | 1. the second se |
| Category | ante |
| Туре | |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

| 1000000 | |
|--|-------------|
| ********* | |
| ******** | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-01-30 |
| Last registration | 2024-02-02 |
| Complete history | See info |



| Registration #1 | 2017-01-30 | 19 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-02-05 | 35.642 mi |
| Registration #3 | 2021-02-05 | 41.877 mi |
| Registration #4 | 2022-02-02 | 50.254 mi |
| Registration #5 | 2022-02-02 | 50.254 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.117 est |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 80% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 73% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1920 mm |
| Height | 1925 mm |
| Length | 5150 mm |
| Wheel base | 3200 mm |
| Kerb weight | 2238 kg |
| Max. allowed weight | 3070 kg |
| Additional information | |
| Fuel tank capacity | 75 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 8 page 12/12 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | D4CBG164710 |