





General information

Make	ΤΟΥΟΤΑ
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	White
Year of manufacture	2014
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	169 BHP
Max. torque	360 Nm at 3.200 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.8 mpg
CO2 emission	227 g/km
CO2 label	L





Internet history

Entry	1
Date	


Pictures

2022-01-09

20

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-26
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	14
Total items failed	0

MOT #8	2023-06-27 13:45
MOT test number	320016054928
Result	✓ Passed
Next expiry date	2024-06-26
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deterio	rated (6.1.7 (g) (i))
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #7		2023-06-27 09:03
MOT test	number	760022018356
Result		🗙 Failed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deter	iorated (6.1.7 (g) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #6	2022-04-07 08:06
MOT test number	995023419613
Result	✓ Passed
MOT #5	2021-04-19 08:59

MOT test number	240763258502
Result	✓ Passed





MOT #4		2020-08-15 09:03
MOT test	number	102387415548
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Nail in tyre	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.2	1.7 (g) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Nail in tyre	

MOT #3	2019-07-27 10:00
MOT test number	538731970685
Result	✓ Passed
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	

MOT #2	2018-08-14 11:32
MOT test number	886447915794
Result	✓ Passed
MOT #1	2017-08-21 09:12
MOT test number	489566203519
Result	✓ Passed



Tax & MOT check

	✓ Taxed		✓ МОТ
Tax due: 1 June 2024 Tax status		Expires: 26 June 2024	Valid until 1 June
Days left			32
MOT expiry date			26 June 2024
Full MOT history			See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-06-16
Last registration	2023-06-27
Complete history	See info



Registration #1	2014-06-16	8 mi
Registration #2	2017-08-21	12.209 mi
Registration #3	2018-08-14	20.860 mi
Registration #4	2019-07-27	26.585 mi
Registration #5	2020-08-15	32.381 mi
Registration #6		11.177 esi
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		11.177 esi
Registration #10		10.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
50567	
S0569	

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Wheel base	3085 mm
Kerb weight	2150 kg
Max. allowed weight	3080 kg

Additional information

	_
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1KDA344277