





report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	White
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-08-02

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-31

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

Advice

MOT expiry date	2024-08-10
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #13	2023-08-03 13:34
MOT test number	566857185719
Result	✓ Passed
Next expiry date	2024-08-10

MOT #12	2022-07-26 07:16
MOT test number	141887611803
Result	✓ Passed

MOT #11	2021-08-11 14:11
MOT test number	538581156237
Result	✓ Passed

MO	T #10	20.	20-07-27 08:59
МО	T test	number	302210046484
Res	sult		✓ Passed
A	dvice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
A	dvice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
A	dvice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/12



VK60EVT

report date: 2024-03-29

MOT #9 2019-05-21 11:32

MOT test number 549176549725

Result ✓ Passed

MOT #8 2019-05-21 08:54

MOT test number 719551417554

Result X Failed

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #7 2018-04-26 09:30

MOT test number 970470459119

Result \(\sqrt{Passed} \)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Rear Tyre wearing on outer edge

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #6 2017-05-16 11:19

MOT test number 541122894185

Result

Passed

MOT #5 2017-05-16 11:19

MOT test number 514308757365

Result × Failed

Pass with rectification Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 4/12



Result

VK60EVT report date: 2024-03-29

✓ Passed

MOT test number

Result

Advice
Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Offside Rear Tyre worn close to the legal limit outer edge 2-3mm (4.1.E.1)

Advice
Nearside Rear Tyre worn close to the legal limit outer edge 2mm (4.1.E.1)

Advice Nearside Near Tyre worn close to the legal limit outer eage	211111 (4.1.L.1)
MOT #3	2015-07-06 12:44
MOT test number	278487785437
Result	✓ Passed
MOT #2	2014-07-16 17:26
MOT test number	438427894184
Result	✓ Passed
MOT #1	2013-08-27 10:18
MOT test number	628439633268

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	С
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-

CarCheck.co.uk page 6/12



VK60EVT

report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

HEREER PARTY NAMED IN COLUMN TO THE PARTY NAM	

	More info >
	More mio
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Correct registration	NK SIE
Plate since	
Current registration	IIK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



VK60EVT

report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-23
Last registration	2023-08-03
Complete history	See info



Registration #1	2010-09-23	14 mi
Registration #2	2013-08-27	8.498 mi
Registration #3	2014-07-16	10.587 mi
Registration #4	2015-07-06	20.237 mi
Registration #5	2016-06-27	29.860 mi
Registration #6	2017-05-16	38.875 mi
Registration #7	2017-05-16	38.875 mi
Registration #8	2018-04-26	42.424 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1016382

CarCheck.co.uk page 12/12