



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVTI GX
Colour	Beige
Year of manufacture	2003
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	146 BHP
Max. torque	193 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-08
Pictures	23
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-11-29
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	37
Total items failed	10

MOT #18	2020-11-30 19:56
MOT test number	637137638541
Result	✓ Passed
Next expiry date	2021-11-29
Advice	Underbody has corrosion
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Underbody covers fitted
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Fuel tank has corrosion
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2020-11-27 12:23

**MOT test number**

953904476201

**Result****✗ Failed**

- Advice** Fuel tank has corrosion
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Underbody has corrosion
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Underbody covers fitted

**MOT #16**

2019-05-28 15:49

**MOT test number**

651303418966

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Underbody has corrosion
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Fuel tank has corrosion

**MOT #15** 2019-05-23 08:44**MOT test number** 873618094024**Result** ✗ Failed

- Advice** Underbody has corrosion
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Fuel tank has corrosion
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #14** 2018-05-24 16:06**MOT test number** 137684055515**Result** ✓ Passed

- Advice** Advise inner sills slight corrosion
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13** 2017-05-24 12:46**MOT test number** 571757080844**Result** ✓ Passed

- Advice** Advise both rear inner sills slight corrosion
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #12** 2016-04-04 09:25**MOT test number** 315969507089**Result** ✓ Passed

- Advice** Advise both rear inner sills slight corrosion

**MOT #11** 2015-03-24 11:53**MOT test number** 748273585043**Result** ✓ Passed**MOT #10** 2014-03-25 14:58**MOT test number** 847204584080**Result** ✓ Passed**MOT #9** 2014-03-21 13:17**MOT test number** 357970784075**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)**MOT #8** 2013-03-04 15:06**MOT test number** 169603263017**Result** ✓ Passed**Notice** Advise brake pipes greased**MOT #7** 2011-12-05 16:58**MOT test number** 159829731373**Result** ✓ Passed**Notice** Advise slight play on steering rack bushes**Notice** Advise main brake pipes greased**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2010-11-26 10:47**MOT test number** 244490530368**Result** ✓ Passed**MOT #5** 2009-11-23 14:38**MOT test number** 960757629384**Result** ✓ Passed**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**MOT #4** 2008-11-20 12:26**MOT test number** 482195528439**Result** ✓ Passed**Notice** ADVISE STEERING RACK BUSHES SLIGHT PLAY**MOT #3** 2008-11-19 12:22**MOT test number** 814824428344**Result** ✗ Failed**Notice** ADVISE STEERING RACK BUSHES SLIGHT PLAY**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2007-10-16 10:36**MOT test number** 393689087201**Result** ✓ Passed



MOT #1	2006-10-16 10:46
MOT test number	902069186229
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Offside front tyre has screw embedded in tread (possible puncture)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

X

Untaxed

Tax expired:  
30 November 2021

X

MOT

Expired:  
29 November 2021

Tax status	Expired at 30 November 2021
Days left	882 days too late
MOT expiry date	29 November 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-10-17
Last registration	2020-11-30
Complete history	<a href="#">See info</a>



Registration #1	2003-10-17	17 mi
Registration #2	2006-10-16	42.017 mi
Registration #3	2007-10-16	53.704 mi
Registration #4	2008-11-19	64.741 mi
Registration #5	2008-11-20	64.792 mi
Registration #6	2009-11-23	72.422 mi
Registration #7	2010-11-26	78.814 mi
Registration #8	2011-12-05	85.310 mi
Registration #9	2013-03-04	93.801 mi
Registration #10	2014-03-21	99.194 mi
Registration #11	2015-03-21	105.586 mi
Registration #12	2016-03-21	111.978 mi
Registration #13	2017-03-21	118.370 mi
Registration #14	2018-03-21	124.762 mi
Registration #15	2019-03-21	131.154 mi
Registration #16	2020-03-21	137.546 mi
Registration #17	2021-03-21	143.938 mi
Registration #18	2022-03-21	150.330 mi
Registration #19	2023-03-21	156.722 mi
Registration #20	2024-03-21	163.114 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ1012713