



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Silver
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



£199
TO RESERVE
THIS CAR
0121 389 4457
www.assuredcarssupermarket.co.uk

Why Buy From US!

- * Drive Away Insurance (t&c)
- * All Cars HPI Checked
- * Nationwide Delivery Aviable
- * Part Exchanges
- * All Cars Prepared And Ready To Go
- * Over 200 Cars To Choose From
- * Leave Deposit To Secure This Vehicle



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-05
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	30
Total items failed	6

MOT #11	2023-06-27 13:30
---------	------------------

MOT test number	736390669636
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-05
------------------	------------

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement inner & outer bush (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement inner & outer bush (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #10**

2023-06-27 08:08

MOT test number

698618652663

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement inner & outer bush (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement inner & outer bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Service brake lagging in operation (1.2.1 (d))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front brake pads worn

MOT #9

2022-06-17 11:10

MOT test number

705411189495

Result

✓ Passed

- Advice** Exhaust corroding

MOT #8

2021-07-06 15:12

MOT test number

229437216929

Result

✓ Passed

MOT #7

2020-11-07 16:18

MOT test number

863487559847

Result

✓ Passed

**MOT #6**

2020-11-06 13:45

MOT test number

489893123829

Result**✗ Failed****Fail**

Tyre tread depth below requirements of 1.6mm both front (5.2.3 (e))

MOT #5

2018-10-04 11:09

MOT test number

780291378151

Result**✓ Passed****Advice**

Power steering pump has slight seepage (2.1.5 (a))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4

2018-10-04 11:09

MOT test number

899760374122

Result**✗ Failed****Advice**

Power steering pump has slight seepage (2.1.5 (a))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3**

2017-08-12 09:04

MOT test number

399960247319

Result

✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2**

2017-08-12 09:04

MOT test number

674778555952

Result

✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1**

2016-08-08 14:47

MOT test number

334987163314

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-06
Last registration	2023-06-27
Complete history	See info



Registration #1	2013-05-06	23 mi
Registration #2	2016-08-08	31.692 mi
Registration #3	2017-08-12	49.861 mi
Registration #4	2017-08-12	49.861 mi
Registration #5	2018-10-04	62.689 mi
Registration #6	2018-10-04	62.689 mi
Registration #7	2020-11-06	77.412 mi
Registration #8	2023-06-27	91.277 mi
Registration #9	2023-06-27	91.277 mi
Registration #10	2023-06-27	91.277 mi
Registration #11	2023-06-27	91.277 mi
Registration #12	2023-06-27	91.277 mi
Registration #13	2023-06-27	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1936 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 286966K LNQ