



RENAULT

YSIILWA


report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI FAP
Colour	Blue
Year of manufacture	2011
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-12-29
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	42
Total items failed	9

MOT #14	2022-01-24 10:06
MOT test number	630937624912
Result	✓ Passed
Next expiry date	2023-01-23
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2022-01-24 10:06
MOT test number	839283508523
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #12**

2021-08-13 11:43

MOT test number

940253428210

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Direction indicator slightly discoloured Both (4.4.3 (a))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #11**

2021-08-12 11:23

MOT test number

674178533473

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Direction indicator slightly discoloured Both (4.4.3 (a))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10**

2020-08-11 12:45

MOT test number

465784469874

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2020-08-11 09:28

MOT test number

645372660256

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)

MOT #8

2019-08-19 08:22

MOT test number

173081859990

Result**✓ Passed**

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #7**

2018-08-17 12:37

MOT test number

889233598818

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt 3rd row seat
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside rear tyre cracking
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Slightly perished (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Chip in zone B of windscreen less than 40mm
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Slightly perished (5.3.4 (a) (i))

MOT #6

2018-08-03 14:36

MOT test number

582421341871

Result

✗ Failed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Slightly perished (5.3.4 (a) (i))
- Advice** Offside rear tyre cracking
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt 3rd row seat
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Chip in zone B of windscreen less than 40mm
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Slightly perished (5.3.4 (a) (i))

**MOT #5** 2017-08-25 09:06**MOT test number** 314100783746**Result** ✓ Passed**Advice** Emissions tested no reading detected**MOT #4** 2016-10-12 09:41**MOT test number** 187326916036**Result** ✓ Passed**MOT #3** 2015-09-30 12:59**MOT test number** 344048906783**Result** ✓ Passed**Advice** Child seats fitted**Advice** N/s/r tyre slightly perrished**MOT #2** 2014-10-23 09:18**MOT test number** 716756194200**Result** ✓ Passed**MOT #1** 2014-06-24 14:42**MOT test number** 287355574488**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YS11LWA
Plate since	2019-03-29
Current registration	YS11LWA
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-08-19
Last registration	2022-01-24
Complete history	See info



Registration #1	2011-08-19	27 mi
Registration #2	2014-06-24	24.025 mi
Registration #3	2014-10-23	25.942 mi
Registration #4	2015-09-30	33.391 mi
Registration #5	2016-10-12	42.241 mi
Registration #6	2017-08-25	49.282 mi
Registration #7	2018-08-03	56.309 mi
Registration #8	2018-08-17	56.536 mi
Registration #9	2019-05-29	56.536 mi
Registration #10	2019-05-29	56.536 mi
Registration #11	2019-05-29	56.536 mi
Registration #12	2019-05-29	56.536 mi
Registration #13	2019-05-29	56.536 mi
Registration #14	2019-05-29	56.536 mi
Registration #15	2019-05-29	56.536 mi
Registration #16	2019-05-29	56.536 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

D172973