





#### General information Make CITROEN Model C4 GRAND E-HDI AIRDREAM EXCLUSIVE PLUS ETG6 Colour Black Year of manufacture 2014 **Top speed** 117 mph 0 - 60 mph 12.6 seconds Gearbox 6 speed Semi-Automatic

### Engine & fuel consumption

| Power                   | 113 BHP             |
|-------------------------|---------------------|
| Max. torque             | 270 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 62.8 mpg            |
| Consumption extra urban | 74.3 mpg            |
| Consumption combined    | 70.6 mpg            |
| CO2 emission            | 105 g/km            |
| CO2 label               | В                   |





| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2021-05-31  |
| Pictures         | 1           |
| Listing price    | View report |



source: autoonline.co.uk



# MOT history

| MOT expiry date    | 2024-06-10 |
|--------------------|------------|
| MOT pass rate      | 88 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 1          |
| Total advice items | 13         |
| Total items failed | 2          |

| MOT #8  |  | 2023-06-09 11:06 |
|---|--|------------------|
| MOT test  | number   | 747966127740     |
| Result  |  | ✓ Passed         |
| Next expi   | iry date   | 2024-06-10       |
| Advice  | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))   |                  |
| Advice  | Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge shoulders (5.2.3 (e))      |                  |
| Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge shoulder sight (5.2.3 (e)) |  | (5.2.3 (e))      |
| Advice  | Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))                                  |                  |
| Advice  | <b>dvice</b> Offside Front Inner Tyre worn close to legal limit/worn on edge shoulders (5.2.3 (e)) |                  |
| Advice  | Offside Rear Tyre worn close to legal limit/worn on edge and age cracks (5.2.3 (                   | e))              |

| MOT #7   | 202  | 22-06-10 11:00 |
|--|--|----------------|
| MOT test   | number   | 611192715618   |
| Result   |  | ✓ Passed       |
| <ul> <li>Advice Offside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))</li> <li>Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner and outer shoulders</li> </ul> |  | houlders       |
| (5.2.3 (e))  | Nearside Front Tyre worn close to legal limit/worn on edge worn on inner and outer s | liouiders      |
| Advice   | Slight age cracks to o/s rear tyre   |                |





| MOT #6  | 2021-06-11 11:24 |  |
|---|------------------|--|
| MOT test number   | 825391792134     |  |
| Result  | ✓ Passed         |  |
|   |                  |  |
| MOT #5  | 2020-10-01 08:52 |  |
| MOT test number   | 474065170503     |  |
| Result  | ✓ Passed         |  |
| Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) |                  |  |
|   |                  |  |

| MOT #4  | 2019-10-02 14:29 |  |
|---|------------------|--|
| MOT test number   | 467214074977     |  |
| Result  | ✓ Passed         |  |
| <b>Minor</b> Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |                  |  |

| MOT #3          | 2018-10-24 15:43 |
|-----------------|------------------|
| MOT test number | 804839813356     |
| Result          | ✓ Passed         |

| MOT #2   | 2017-03-27 13:41 |
|--|------------------|
| MOT test number                                | 356359036446     |
| Result   | ✓ Passed         |
| Advice Rear Brake pad(s) wearing thin (3.5.1g) |                  |

| MOT #1   | 2017-03-27 09:28 |  |
|--|------------------|--|
| MOT test number  | 296210435819     |  |
| Result   | 🗙 Failed         |  |
| <b>Fail</b> Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b) |                  |  |
| Fail         Nearside Registration plate lamp not working (1.1.C.1d)   |                  |  |
| Advice Rear Brake pad(s) wearing thin (3.5.1g)   |                  |  |



Tax & MOT check

| <b>Tax due:</b><br>1 June 2024 | ✓<br>Taxed | <b>Expires:</b><br>10 June 2024 | √<br>мот           |
|--------------------------------|------------|---------------------------------|--------------------|
| Tax status                     |            |                                 | Valid until 1 June |
| Days left                      |            |                                 | 34                 |
| MOT expiry date                |            |                                 | 10 June 2024       |
| Full MOT history               |            |                                 | See MOT history    |
| Tax calculation                |            |                                 |                    |

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | В              |
| Single payment (12 months)              | £ 20,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,-      |





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     |         |
| Category | Lamp    |
| Туре     |         |
| Damage 2 | AMPL    |
|          | E Store |
| Date     | 1. E    |
| Category | amt     |
| Туре     |         |

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |





### Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| *******  |             |
|--|-------------|
| ************   |             |
| ********   |             |
| ******   |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this CITROEN had different number plates. |             |
| Number of plates   |             |
| Carrent registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2014-03-24 |
| Last registration          | 2023-06-09 |
| Complete history           | See info   |



| Registration #1  | 2014-03-24 | 17 mi      |
|------------------|------------|------------|
| Registration #2  | 2017-03-27 | 34.701 mi  |
| Registration #3  | 2017-03-27 | 34.706 mi  |
| Registration #4  | 2018-10-24 | 35.658 mi  |
| Registration #5  | 2019-10-02 | 42.397 mi  |
| Registration #6  |            | 11.777 est |
| Registration #7  |            | 11.777 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            |            |

More info >





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 90%             |
| Children       | 85%             |
| Pedestrian     | 43%             |
| Safety systems | 97%             |
| Overall rating | 80%             |
| Video          | see crash video |



| Dimensions & weight                                    |                          |
|--|--------------------------|
| Width  | 1826 mm                  |
| Height   | 1656 mm                  |
| Length   | 4597 mm                  |
| Wheel base   | 2840 mm                  |
| Kerb weight  | 1320 kg                  |
| Max. allowed weight                                    | 2150 kg                  |
|  |                          |
| Additional information                                 |                          |
| Additional information Fuel tank capacity              | 55 l                     |
|  | 55 l<br>Direct Injection |
| Fuel tank capacity                                     |                          |
| Fuel tank capacity<br>Fuel delivery                    | Direct Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Direct Injection<br>5    |