





report date: 2024-03-29

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Silver
Year of manufacture	2008
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	200 g/km
CO2 label	1



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2022-01-06
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #11	2020-12-11 15:27
MOT test number	890817224049
Result	✓ Passed
Next expiry date	2022-01-06

MOT #10	2020-12-11 08:42	
MOT test number	798665348169	
Result	X Failed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor (b) (i)) Offside Front Lower Suspension arm ball joint dust cover severely deteriorate	ed in hub carrier (5.3.4	

MOT #9	2019-12-14 13:10
MOT test number	447921925157
Result	✓ Passed

MOT #8	2019-01-07 14:05
MOT test number	913220453342
Result	✓ Passed

CarCheck.co.uk page 2/10



YN08NYO

report date: 2024-03-29

MOT #7 2017-01-03 12:11

MOT test number 545377267350

MOT #6 2016-12-24 15:48

MOT test number 637136982304

Result ★ Failed

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Front Inner Tyre worn close to the legal limit Edge. (4.1.E.1)

MOT #5 2015-12-21 10:11

MOT test number 649400885958

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement o/s n/s (2.4.G.2)

Advice Front Suspension arm has slight play in a ball joint o/s n/s (2.4.G.2)

MOT #4 2014-09-22 12:30

MOT test number 986425164205

MOT #3 2013-05-08 14:28

MOT test number 858488223154

Result

Passed

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Front tyres wearing on inside edges

CarCheck.co.uk page 3/10



MOT #2 2012-05-03 10:55

MOT test number 475114222123

Result ✓ Passed

Notice OSR tyre has slight sidewall damage

MOT #1 2011-05-11 15:48

MOT test number 747341131180

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



OYN80NY

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK WE
Plate since	
Current registration	UK NEW
Plate since	
	More info >

CarCheck.co.uk page 7/10



OYN80NY

report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2008-03-07
Last registration	2020-12-11
Complete history	See info



Registration #1	2008-03-07	9 mi
Registration #2	2011-05-11	28.233 mi
Registration #3	2012-05-03	46.773 mi
Registration #4	2013-05-08	71.535 mi
Registration #5	2014-09-22	87.343 mi
Registration #6	2015-12-21	96.710 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040688805

CarCheck.co.uk page 10/10