



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 115
Colour	Grey
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	38
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #22	2021-10-08 14:20
MOT test number	836282270628
Result	✓ Passed
Next expiry date	2022-10-07

MOT #21	2021-09-30 13:28
MOT test number	179597482554
Result	✗ Failed

- Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Headlamp aim not tested (4.1.2 (b))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #20	2020-09-30 13:31
MOT test number	533918168671
Result	✓ Passed

MOT #19	2020-09-30 09:36
MOT test number	246432734832
Result	✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #18** 2019-09-25 14:56**MOT test number** 207833208474**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2019-09-25 10:56**MOT test number** 952259452269**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #16** 2018-09-27 09:23**MOT test number** 310935295823**Result** ✓ Passed**MOT #15** 2017-09-21 13:29**MOT test number** 208250448537**Result** ✓ Passed

**MOT #14**

2017-09-21 09:24

MOT test number

171101624388

Result**✗ Failed**

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

MOT #13

2016-09-08 13:58

MOT test number

305477936761

Result**✓ Passed**

- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Front Non obligatory mirror damaged
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #12

2016-09-08 09:18

MOT test number

698506459392

Result**✗ Failed**

- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Front Non obligatory mirror damaged
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #11** 2015-09-29 07:44**MOT test number** 940796167317**Result** ✓ Passed**MOT #10** 2015-09-19 11:57**MOT test number** 990514515452**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2014-08-14 12:09**MOT test number** 346896724447**Result** ✓ Passed**MOT #8** 2013-08-15 13:06**MOT test number** 368917923497**Result** ✓ Passed**MOT #7** 2013-08-15 13:06**MOT test number** 889327823228**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #6** 2012-08-16 16:46**MOT test number** 859139022252**Result** ✓ Passed**MOT #5** 2011-08-11 09:48**MOT test number** 788583621219**Result** ✓ Passed

**MOT #4** 2010-08-13 15:13**MOT test number** 364425620288**Result** ✓ Passed**MOT #3** 2010-08-13 15:13**MOT test number** 143545320276**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2009-09-09 16:15**MOT test number** 500682959259**Result** ✓ Passed**Notice** N/s/rear lens unit slight damage**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Heatshield loose above front exhaust section**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2009-08-27 11:32**MOT test number** 761589639268**Result** ✗ Failed**Fail** Parking brake lever defective so that it cannot be satisfactorily operated (3.1.3c)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-04
Last registration	2021-10-08
Complete history	See info



Registration #1	2006-09-04	25 mi
Registration #2	2009-08-27	38.701 mi
Registration #3	2009-09-09	38.702 mi
Registration #4	2010-08-13	44.083 mi
Registration #5	2011-08-11	48.876 mi
Registration #6	2012-08-16	54.617 mi
Registration #7	2013-08-15	61.760 mi
Registration #8	2014-08-14	69.448 mi
Registration #9	2015-09-19	1.598 mi
Registration #10	2015-09-29	75.192 mi
Registration #11	2016-09-08	84.326 mi
Registration #12	2016-09-08	84.326 mi
Registration #13	2016-09-08	84.326 mi
Registration #14	2016-09-08	84.326 mi
Registration #15	2016-09-08	84.326 mi
Registration #16	2016-09-08	84.326 mi
Registration #17	2016-09-08	84.326 mi
Registration #18	2016-09-08	84.326 mi
Registration #19	2016-09-08	84.326 mi
Registration #20	2016-09-08	84.326 mi
Registration #21	2016-09-08	84.326 mi
Registration #22	2016-09-08	84.326 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Kerb weight	1365 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	D045471