



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2024-10-25
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	34
Total items failed	14

MOT #19	2023-10-26 06:45
MOT test number	283286523728
Result	✓ Passed
Next expiry date	2024-10-25
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2022-10-15 13:12
MOT test number	140112008964
Result	✓ Passed

MOT #17	2022-10-15 09:01
MOT test number	567696483826
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16	2021-09-21 08:02
MOT test number	310172277987
Result	✓ Passed
Advice	Rear Coil spring corroded Both sides (5.3.1 (b) (i))



MOT #15	2020-09-29 15:02
MOT test number	238952230066
Result	✓ Passed
Advice	Rear exhaust hangers corroded

MOT #14	2020-09-29 09:51
MOT test number	254146802712
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Rear exhaust hangers corroded
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13	2019-09-13 15:01
MOT test number	395545988185
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt all rear set belts not checked
Advice	Rear exhaust hanger very corrode and thin

**MOT #12**

2019-09-13 11:36

MOT test number

501954124300

Result**✗ Failed**

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear exhaust hanger very corrode and thin

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Child Seat fitted not allowing full inspection of adult belt all rear set belts not checked

Fail Offside Rear Anti-roll bar linkage pin or bush excessively worn broken (5.3.4 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Nail in tyre both rear tyres

MOT #11

2018-09-12 11:40

MOT test number

518690578993

Result**✓ Passed**

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Nail in tyre 2 nails

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10

2017-09-15 14:18

MOT test number

302807139869

Result**✓ Passed**

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2017-09-15 09:58**MOT test number** 710308148811**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #8** 2016-09-15 09:19**MOT test number** 837267217274**Result** ✓ Passed**MOT #7** 2015-09-29 13:06**MOT test number** 799588186045**Result** ✓ Passed**MOT #6** 2015-09-29 10:09**MOT test number** 654900986959**Result** ✗ Failed**Advice** Front wipers not checked**Fail** Windscreen washer provides insufficient washer liquid All washers / leaking (8.2.3)**MOT #5** 2014-09-24 13:35**MOT test number** 389837964289**Result** ✓ Passed

**MOT #4**

2014-09-23 11:02

MOT test number

598036164208

Result**✗ Failed**

- Fail** Offside Body has a sharp edge caused by damage (6.1.C.1)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Side repeater not working (1.4.A.2c)
- Notice** Nearside rear tyre deteriorated /cracking to tread
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2013-09-17 15:14

MOT test number

696060763281

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test

MOT #2

2013-09-17 15:14

MOT test number

685140663281

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-07-30 11:50
MOT test number	459772912222
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-11
Last registration	2023-10-26
Complete history	See info



Registration #1	2009-09-11	12 mi
Registration #2	2012-07-30	25.218 mi
Registration #3	2013-09-17	34.346 mi
Registration #4	2014-09-23	41.302 mi
Registration #5	2014-09-24	41.302 mi
Registration #6	2015-09-29	49.158 mi
Registration #7	2015-09-29	49.158 mi
Registration #8	2016-09-15	50.430 mi
Registration #9	2017-09-15	52.251 mi
Registration #10	2017-09-15	52.251 mi
Registration #11	2018-09-15	52.251 mi
Registration #12	2018-09-15	52.251 mi
Registration #13	2018-09-15	52.251 mi
Registration #14	2018-09-15	52.251 mi
Registration #15	2018-09-15	52.251 mi
Registration #16	2018-09-15	52.251 mi
Registration #17	2018-09-15	52.251 mi
Registration #18	2018-09-15	52.251 mi
Registration #19	2018-09-15	52.251 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607