



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	-
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg







LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-26
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #14	2022-03-02 17:15
MOT test number	755059448238
Result	✓ Passed
Next expiry date	2023-03-01
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Odometer illegible
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-03-01 16:23
MOT test number	593791666769
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-04-20 15:43
MOT test number	303798971159
Result	✓ Passed

MOT #11	2020-02-04 14:19
MOT test number	542154902334
Result	✓ Passed

MOT #10	2020-02-03 11:47
MOT test number	618037277788
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2019-01-06 11:30**MOT test number** 280452342277**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2018-01-02 12:30**MOT test number** 976939089244**Result** ✓ Passed**MOT #7** 2016-12-21 13:43**MOT test number** 265579451644**Result** ✓ Passed**Advice** Under trays fitted**MOT #6** 2015-10-24 09:43**MOT test number** 617132568102**Result** ✓ Passed**Advice** Under trays fitted**Advice** Covers in engine bay**MOT #5** 2014-10-25 08:53**MOT test number** 469128394202**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Items removed from driver's view prior to test**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-10-25 08:53**MOT test number** 575678994284**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Front registration plate character(s) likely to be misread (6.3.4b)**Notice** Items removed from driver's view prior to test**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-10-25 15:41**MOT test number** 855438593200**Result** ✓ Passed**MOT #2** 2013-10-25 11:37**MOT test number** 686518093228**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2012-10-31 08:59**MOT test number** 956295202352**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-12-22
Last registration	2022-03-02
Complete history	See info



Registration #1	2009-12-22	25 mi
Registration #2	2012-10-31	44.679 mi
Registration #3	2013-10-25	52.849 mi
Registration #4	2013-10-25	52.849 mi
Registration #5	2014-10-25	59.567 mi
Registration #6	2015-10-24	67.065 mi
Registration #7	2016-12-21	74.434 mi
Registration #8	2019-05-29	91.277 mi
Registration #9	2019-05-29	91.277 mi
Registration #10	2019-05-29	91.277 mi
Registration #11	2019-05-29	91.277 mi
Registration #12	2019-05-29	91.277 mi
Registration #13	2019-05-29	91.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9E87491