



DV04FRU

report date: 2024-03-28

General information

Make	NISSAN
Model	PICKUP DCB NAVARA OUTLAW 4X4 P/U
Colour	Silver
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	131 BHP
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT expiry date	2020-10-28
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	19
Total items failed	19

MOT #18	2019-01-10 15:47
MOT test number	385112983271
Result	✓ Passed
Next expiry date	2020-01-14
Advice	Fuel Pipe/s corroded
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #17	2018-01-15 16:56
MOT test number	637740398724
Result	✓ Passed
Advice	Offside Rear Service brake grabbing slightly (3.7.C.2)

MOT #16	2017-01-10 16:59
MOT test number	323377773789
Result	✓ Passed

**MOT #15** 2016-12-21 08:41**MOT test number** 223793852957**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #14** 2015-10-16 11:26**MOT test number** 878917273712**Result** ✓ Passed**MOT #13** 2015-10-15 15:15**MOT test number** 535352333198**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #12** 2014-10-15 10:55**MOT test number** 215088284271**Result** ✓ Passed**Notice** Rear(over axle) and nearside brake pipes showing corrosion (treated no further action required)**Notice** Tow electrics not tested (no eu standard for 7 pin plugs)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2014-10-15 10:55

MOT test number

676358584226

Result**✗ Failed**

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Tow electrics not tested (no eu standard for 7 pin plugs)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Notice Rear(over axle) and nearside brake pipes showing corrosion (treated no further action required)

MOT #10

2013-08-01 12:58

MOT test number

546703213212

Result**✓ Passed****MOT #9**

2013-08-01 10:15

MOT test number

956083913259

Result**✗ Failed**

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Notice Front tyres worn

Fail Rear Exhaust system not adequately supported (7.1.1)

Fail Registration plate lamp not working (1.1.C.1d)

Fail Offside Rear position lamp(s) not working (1.1.A.3b)

Notice Steering bump stops require greasing

Fail Offside rear brake binding (3.7.B.1)

**MOT #8** 2012-08-03 17:01**MOT test number** 616916012231**Result** ✓ Passed**Notice** Rear exhaust bracket broken**Notice** Slight oil leak from gear box area**MOT #7** 2011-09-06 12:14**MOT test number** 739409141211**Result** ✓ Passed**MOT #6** 2011-09-02 17:15**MOT test number** 829295141298**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2010-07-23 14:57**MOT test number** 434314200207**Result** ✓ Passed**MOT #4** 2010-07-23 11:43**MOT test number** 124434300232**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside rear brake binding (3.7.B.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2009-06-11 15:32
MOT test number	722322469182
Result	✓ Passed
<div>Notice Front number plate in poor condition</div>	

MOT #2	2008-03-27 15:18
MOT test number	792987888097
Result	✓ Passed

MOT #1	2007-03-29 08:44
MOT test number	684628387008
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2020

✕
MOT

Expired:
28 October 2020

Tax status	Expired at 31 January 2020
Days left	1551 days too late
MOT expiry date	28 October 2020
Full MOT history	See MOT history



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-03-24
Last registration	2019-01-10
Complete history	See info



Registration #1	2004-03-24	21 mi
Registration #2	2007-03-29	45.249 mi
Registration #3	2008-03-27	62.223 mi
Registration #4	2009-06-11	76.084 mi
Registration #5	2010-07-23	88.630 mi
Registration #6	2010-07-23	88.630 mi
Registration #7	2011-09-02	95.737 mi
Registration #8	2011-09-06	95.737 mi
Registration #9	2012-08-03	102.569 mi
Registration #10	2013-05-20	111.377 mi
Registration #11	2014-05-20	121.377 mi
Registration #12	2015-05-20	131.377 mi
Registration #13	2016-05-20	141.377 mi
Registration #14	2017-05-20	151.377 mi
Registration #15	2018-05-20	161.377 mi
Registration #16	2019-05-20	171.377 mi
Registration #17	2020-05-20	181.377 mi
Registration #18	2021-05-20	191.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Engine number	093374