



report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS CRDI
Colour	Silver
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	12.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	191 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-12-13
Pictures	3
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-06-22
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	55
Total items failed	21

MOT #19	2022-06-23 17:29
MOT test number	663763143384
Result	✓ Passed
Next expiry date	2023-06-22
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm foremost bush (5.3.4 (a) (i))
Advice	Offside Rear tyre starting to show signs of cracking and perishing
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm foremost bush (5.3.4 (a) (i))

**MOT #18**

2022-05-25 13:48

MOT test number

335526571809

Result**✗ Failed**

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Front Inner Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

Fail Nearside Rear Seat belt buckle missing (7.1.2 (d))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Advice Fluid leak, but not excessive diesel (8.4.1 (a) (i))

MOT #17

2021-05-26 12:04

MOT test number

326438772965

Result**✓ Passed**

Advice Engine management light illuminated

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #16**

2021-05-26 09:41

MOT test number

170043419227

Result**✗ Failed**

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Advice Engine management light illuminated

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #15

2020-06-17 09:55

MOT test number

716875726746

Result**✓ Passed**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Nail in tyre

Advice Engine management light illuminated

MOT #14

2019-05-13 15:47

MOT test number

475760083332

Result**✓ Passed**

Advice Fuel tank heat shield insecure

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Engine management light illuminated

**MOT #13**

2018-05-14 13:43

MOT test number

518752638047

Result

✓ Passed

- Advice** O/s/f brake binding slightly
- Advice** Both front tyres worn inner edges
- Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)
- Advice** Engine management light illuminated
- Advice** O/s/r tyre worn inner edge

MOT #12

2018-05-14 11:16

MOT test number

839697911111

Result

✗ Failed

- Advice** Both front tyres worn inner edges
- Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)
- Advice** Engine management light illuminated
- Advice** O/s/r tyre worn inner edge
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** O/s/f brake binding slightly

MOT #11

2017-05-25 10:15

MOT test number

337073115699

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Engine management light illuminated
- Advice** Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)
- Advice** O/s/r tyre worn inner edge

**MOT #10**

2017-05-24 10:41

MOT test number

225064596232

Result

✗ Failed

Advice Both front tyres worn inner edges**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Engine management light illuminated**Advice** Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)**MOT #9**

2016-05-20 08:45

MOT test number

218234781055

Result

✓ Passed

Advice Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #8**

2016-05-18 12:07

MOT test number

993081760847

Result

✗ Failed

Fail Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Rear Valve stem seriously damaged (4.1.D.1e)**Fail** Offside Front Valve stem seriously damaged (4.1.D.1e)**Fail** Front brake application uneven (3.7.B.2)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Fail** Offside Rear Valve stem seriously damaged (4.1.D.1e)**MOT #7**

2015-05-22 14:34

MOT test number

238432745103

Result

✓ Passed

**MOT #6** 2015-05-20 14:58**MOT test number** 666750345121**Result** ✗ Failed

- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front suspension has a suspension lower ball joint securing nut not locked (2.5.B.1a)
- Fail** Nearside Steering locking device missing (2.2.C.1g)
- Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Front suspension has a suspension lower ball joint securing nut not locked (2.5.B.1a)
- Fail** Offside Steering locking device missing (2.2.C.1g)

MOT #5 2014-06-03 07:57**MOT test number** 789244054111**Result** ✓ Passed**MOT #4** 2013-05-18 10:24**MOT test number** 767248033136**Result** ✓ Passed

- Notice** Offside rear tyre badly worn on the inner edge
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2012-05-26 09:45**MOT test number** 387567742160**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Power steering component(s) has slight seepage from a seal (2.3.3b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-05-25 12:02
MOT test number	255065141191
Result	✓ Passed

MOT #1	2010-05-27 11:54
MOT test number	424837240190
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
2 July 2023

✕
MOT

Expired:
22 June 2023

Tax status	Expired at 2 July 2023
Days left	302 days too late
MOT expiry date	22 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YP07VLA
Plate since	2019-03-28
Current registration	YP07VLA
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-01
Last registration	2022-06-23
Complete history	See info



Registration #1	2007-06-01	25 mi
Registration #2	2010-05-27	30.109 mi
Registration #3	2011-05-25	41.690 mi
Registration #4	2012-05-26	51.094 mi
Registration #5	2013-05-18	60.052 mi
Registration #6	2014-06-03	69.199 mi
Registration #7	2015-05-20	78.821 mi
Registration #8	2015-05-22	78.933 mi
Registration #9	2016-05-18	91.671 mi
Registration #10	2016-05-20	91.673 mi
Registration #11	2017-05-24	103.047 mi
Registration #12	2018-05-20	115.277 mi
Registration #13	2019-05-20	127.507 mi
Registration #14	2020-05-20	139.737 mi
Registration #15	2021-05-20	151.967 mi
Registration #16	2022-05-20	164.197 mi
Registration #17	2023-05-20	176.427 mi
Registration #18	2024-05-20	188.657 mi
Registration #19	2025-05-20	200.887 mi
Registration #20	2026-05-20	213.117 mi
Registration #21	2027-05-20	225.347 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1681 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4EA6H24440