





report date: 2024-03-28

General information

Make	KIA
Model	OPTIMA CRDI 2 TECH
Colour	Black
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date	2021-12-22
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-21	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #12	2022-01-25 17:16
MOT test number	639343297930
Result	✓ Passed
Next expiry date	2023-01-24

MOT #	11	2022-01-25 16:20
MOT te	est number	984876239974
Result		× Failed
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Offside Front Road wheel fixing missing wheel nut missing (5.2.1 (a) (i))	
Fail	Tyre has a bulge, caused by separation or partial failure of its structure both side	es rear (5.2.3 (d) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps both	n rear (4.7.1 (b) (ii))
Fail	Brake lever has insufficient reserve travel handbrake (1.1.2 (a))	

MOT #:	2022-01-21 15:22	
MOT te	st number 495921686064	
Result	★ Failed	
Fail	Tyre has a bulge, caused by separation or partial failure of its structure both sides rear (5.2.3 (d) (ii))	
Fail	Offside Front Road wheel fixing missing wheel nut missing (5.2.1 (a) (i))	
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps both rear (4.7.1 (b) (ii))	
Fail	Brake lever has insufficient reserve travel handbrake (1.1.2 (a))	
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #9 2021-11-10 14:30

MOT test number 345485878046

Result X Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside rear tyre sawtoothing at inner edge

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #8 2020-11-30 11:43

MOT test number 527004596907

Result ✓ Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2020-11-30 11:35

MOT test number 651240592730

Result X Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2019-05-30 11:36

MOT test number 335511324533

Result ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #5 2019-05-30 09:56

MOT test number 619556215938

Result × Failed

Fail Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2018-03-08 02:15

MOT test number 689161705902

Result \(\sqrt{Passed} \)

Advice

Nearside Rear Tyre cracked and perished inner/outer.

MOT #3 2018-03-08 02:15

MOT test number 850234075354

Result X Failed

Pass with rectification Front Headlamp aim too high (1.8)

Advice Nearside Rear Tyre cracked and perished inner/outer.

MOT #2 2017-05-06 08:11

MOT test number 499838430312

Result ✓ Passed

MOT #1 2016-05-07 09:20

MOT test number 983040363134

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

,		
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		

	More info	>
Plate changes See in this check if this KIA had different number plates		
See in this check if this KIA had different number plates.		
Number of plates		,
Current registration	NK NE	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-04-30
Last registration	2022-01-25
Complete history	See info



Registration #1	2013-04-30	24 mi
Registration #2	2016-05-07	24.077 mi
Registration #3	2017-05-06	29.160 mi
Registration #4	2018-03-08	31.600 mi
Registration #5	2018-03-08	31.600 mi
Registration #6	2019-05-30	51.827 mi
Registration #7	2019-05-30	51.827 mi
Registration #8	2020-11-30	77.828 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Dimensions & weight

Width	1830 mm
Height	1455 mm
Length	4845 mm
Wheel base	2795 mm
Kerb weight	1637 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	D4FDBH301704

CarCheck.co.uk page 11/11