



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	JETTA SE TDI
Colour	Red
Year of manufacture	-
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	7.1 mpg
Consumption combined	5.5 mpg






Internet history

Entry 1

Date	2021-09-07
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #11</b>	2022-06-06 09:43
<b>MOT test number</b>	237695767219
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-06-05
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #10</b>	2021-03-08 12:04
<b>MOT test number</b>	439215940104
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2020-03-13 17:04
<b>MOT test number</b>	878946305446
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2020-03-13 16:16
<b>MOT test number</b>	471752256704
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Offside Rear Service brake binding but not excessively (1.2.1 (f))

<b>MOT #7</b>	2019-03-22 09:35
<b>MOT test number</b>	480149777072
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2018-03-15 15:24
<b>MOT test number</b>	865498667168
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Nail in tyre

**MOT #5** 2018-03-15 11:25**MOT test number** 761804557643**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Offside Front Nail in tyre**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #4** 2017-02-28 11:05**MOT test number** 316319310331**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-03-03 13:29**MOT test number** 525328631861**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)**MOT #2** 2015-03-10 11:43**MOT test number** 435439065098**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #1	2014-03-20 14:35
MOT test number	849979774059
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>FL11WVE</b>
Plate since	2019-03-29
Current registration	<b>FL11WVE</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-24
Last registration	2022-06-06
Complete history	<a href="#">See info</a>



Registration #1	2011-03-24	21 mi
Registration #2	2014-03-20	97.593 mi
Registration #3	2015-03-10	114.314 mi
Registration #4	2016-03-03	130.468 mi
Registration #5	2017-02-28	145.126 mi
Registration #6	2018-03-15	150.243 mi
Registration #7	2018-03-15	150.243 mi
Registration #8	2019-03-20	151.277 mi
Registration #9	2019-03-20	151.277 mi
Registration #10	2019-03-20	151.277 mi
Registration #11	2019-03-20	151.277 mi
Registration #12	2019-03-20	151.277 mi
Registration #13	2019-03-20	151.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1411 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	NOT KNOWN