



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA HDI VTR PLUS SCORE
Colour	Red
Year of manufacture	2010
Top speed	138 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-09-14
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-28
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	35
Total items failed	11

MOT #17	2024-02-29 07:43
MOT test number	695221820836
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive engine area (8.4.1 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2024-02-20 12:50

MOT test number

486128701294

Result**✗ Failed**

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive engine area (8.4.1 (a) (i))
- Fail** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15

2023-02-04 15:42

MOT test number

592000477127

Result**✓ Passed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)

**MOT #14**

2022-02-15 17:25

MOT test number

258926190181

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2021-02-10 09:16

MOT test number

350790963686

Result

✓ Passed

Advice Nearside Front abs sensor rubs on abs ring**Advice** Play in steering rack inner joint(s) both**MOT #12**

2020-02-11 17:13

MOT test number

927441604528

Result

✓ Passed

Advice Play in steering rack inner joint(s) both**Advice** Nearside mirror damaged**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11**

2019-02-15 15:04

MOT test number

961609037223

Result

✓ Passed

Advice Central brake light**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s)

**MOT #10**

2019-02-14 09:15

MOT test number

700970891522

Result

✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Play in steering rack inner joint(s)**Advice** Central brake light**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2018-02-13 09:02

MOT test number

982666452253

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Advice** Nearside Play in steering rack inner joint(s)**MOT #8**

2017-02-22 13:16

MOT test number

257718629081

Result

✓ Passed

MOT #7

2017-02-21 13:31

MOT test number

130873917906

Result

✗ Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2016-01-15 09:02**MOT test number** 251519603598**Result** ✓ Passed**MOT #5** 2015-01-14 08:35**MOT test number** 938404715038**Result** ✓ Passed**MOT #4** 2015-01-14 08:35**MOT test number** 327574915005**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Centre Rear Passenger's seat insecure (6.2.A.1)**MOT #3** 2014-01-15 14:56**MOT test number** 746535114026**Result** ✓ Passed**MOT #2** 2014-01-15 09:04**MOT test number** 338595414042**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #1** 2013-01-15 09:44**MOT test number** 667665513032**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
28 February 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-20
Last registration	2024-02-29
Complete history	See info



Registration #1	2010-01-20	12 mi
Registration #2	2013-01-15	46.405 mi
Registration #3	2014-01-15	61.913 mi
Registration #4	2014-01-15	61.913 mi
Registration #5	2015-01-14	77.931 mi
Registration #6	2016-01-15	94.333 mi
Registration #7	2017-02-21	110.790 mi
Registration #8	2017-02-22	110.790 mi
Registration #9	2018-02-13	127.007 mi
Registration #10	2019-01-20	143.409 mi
Registration #11	2019-01-20	143.409 mi
Registration #12	2019-01-20	143.409 mi
Registration #13	2019-01-20	143.409 mi
Registration #14	2019-01-20	143.409 mi
Registration #15	2019-01-20	143.409 mi
Registration #16	2019-01-20	143.409 mi
Registration #17	2019-01-20	143.409 mi
Registration #18	2019-01-20	143.409 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1503 kg
Max. allowed weight	2045 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	JBBN0098245