






report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Blue
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Engine capacity	1.986 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-07-03

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-10-05
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	23
Total items failed	7

MOT #18	2023-10-06 16:13
MOT test number	519112351851
Result	✓ Passed
Next expiry date	2024-10-05
Advice Front Lower Suspension arm pin or bush worn but not resulting in excrear bushes (5.3.4 (a) (i))	essive movement Both sides
Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice Brake disc worn, pitted or scored, but not seriously weakened Front a	nd rear (1.1.14 (a) (ii))
Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Both sides trailing arm bushes (5.3.4 (a) (i))	
Advice Front Play in steering rack inner joint(s) Both sides	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely of	deteriorated (6.1.7 (g) (i))
Advice Rear Inner Tyre worn close to legal limit/worn on edge Both sides (5.2	3 (e))

MOT #17	2022-08-13 13:38
MOT test number	533962120256
Result	✓ Passed
MOT #16	2021-08-17 14:11
MOT #16 MOT test number	2021-08-17 14:11 717736424076

CarCheck.co.uk page 3/14



MOT #15 2020-07-07 08:43

MOT test number 413805125683

MOT #14 2019-07-09 15:54

MOT test number 425430476937

Result ✓ Passed

MOT #13 2018-07-11 13:43

MOT test number 906931111890

Result \(\sqrt{Passed} \)

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12 2018-07-11 10:26

MOT test number 891601618622

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11 2017-07-19 12:00

MOT test number 301701487416

Result \(\sqrt{Passed} \)

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

MOT #10 2016-07-12 07:48

MOT test number 720976295076

CarCheck.co.uk page 4/14



MOT #9 2016-07-11 09:42

MOT test number 864529505251

Result × Failed

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Nearside Anti-roll bar linkage severely distorted boot split (2.4.G.1)

MOT #8 2015-06-30 10:42

MOT test number 706881685146

Result \(\sqrt{Passed} \)

Notice Lump on nsr tyre not cause by separation

MOT #7 2014-07-07 09:36

MOT test number 209168384160

Result \rightarrow Passed

MOT #6 2014-07-07 09:36

MOT test number 177368984139

Result X Failed

Pass with rectification Front Brake lining(s) less than 1.5 mm thick (3.5.1g)

MOT #5 2013-07-09 10:20

MOT test number 939550793178

CarCheck.co.uk page 5/14



Rear Brake pad(s) wearing thin (3.5.1g)

Advice

LOO8JHA report date: 2024-03-28

MOT #4

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear coil spring incomplete (2.4.C.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

158884271152

Result

Notice Both rear tyres feathered.

Notice Both rear tyres low on inner edge.

CarCheck.co.uk page 6/14



MOT test number

249764471420

Result

Notice Both rear tyres feathered.

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Both rear tyres low on inner edge.

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Category Type

Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 11/14



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-21
Last registration	2023-10-06
Complete history	See info



Registration #1	2008-07-21	15 mi
Registration #2	2011-06-23	47.245 mi
Registration #3	2012-07-02	53.505 mi
Registration #4	2012-07-02	55.305 mi
Registration #5	2013-07-09	66.899 mi
Registration #6	2014-07-07	74.797 mi
Registration #7	2015-06-30	81.744 mi
Registration #8	2016-07-11	88.897 mi
Registration #9	2016-07-12	88.899 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
	7.4.7.4

CarCheck.co.uk page 14/14

Number of seats	5
Engine number	CBA 067351