



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX HL2 4X4 D-4D DCB
Colour	Blue
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	142 BHP
Max. torque	343 Nm at 2.800 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-05-08
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	23
Total items failed	5

MOT #10	2024-04-17 09:24
MOT test number	945709998482
Result	✓ Passed
Next expiry date	2025-05-08
Advice	Rear floor corroded (bed)
Advice	Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (7.1.1 (a) (i))
Advice	Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Front Coil spring corroded both (5.3.1 (b) (i))
Advice	Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (7.1.1 (a) (i))
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

**MOT #9** 2023-05-09 15:48**MOT test number** 867854796811**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2022-05-11 12:09**MOT test number** 503270241499**Result** ✓ Passed**Advice** Recommend brakes be serviced**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2021-06-10 14:15**MOT test number** 232782800408**Result** ✓ Passed**MOT #6** 2021-06-08 13:57**MOT test number** 692153693691**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #5** 2019-10-22 14:24**MOT test number** 373365462331**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material Front to rear at rear (1.1.11 (c))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #4** 2019-10-09 15:56**MOT test number** 196432101140**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded caliper brake pipe (1.1.11 (c))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Fail** Rear Brake pipe excessively corroded brake pipe at compensatory valve (1.1.11 (c))**Fail** Rear Brakes imbalanced across an axle o/s brake (1.2.1 (b) (i))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Rear Trailer electrical socket likely to become detached (4.10 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material Front to rear at rear (1.1.11 (c))**MOT #3** 2018-10-23 12:36**MOT test number** 795018875697**Result** ✓ Passed**MOT #2** 2017-12-07 09:55**MOT test number** 349363694331**Result** ✓ Passed



MOT #1	2016-11-22 14:31
MOT test number	729863569573
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
8 May 2025

Tax status		Valid until 1 June
Days left		34
MOT expiry date		8 May 2025
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-17
Last registration	2024-04-17
Complete history	<a href="#">See info</a>



Registration #1	2013-12-17	17 mi
Registration #2	2016-11-22	60.427 mi
Registration #3	2017-12-07	84.487 mi
Registration #4	2018-10-23	96.721 mi
Registration #5	2019-10-09	104.861 mi
Registration #6	2019-10-22	104.862 mi
Registration #7	2019-10-22	104.862 mi
Registration #8	2019-10-22	104.862 mi
Registration #9	2019-10-22	104.862 mi
Registration #10	2019-10-22	104.862 mi
Registration #11	2019-10-22	104.862 mi
Registration #12	2019-10-22	104.862 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1850 mm
Length	5260 mm
Kerb weight	1995 kg
Max. allowed weight	3040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	2KDA164161