



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | CITROEN |
| Model | XSARA 16V SX |
| Colour | Red |
| Year of manufacture | - |
| Top speed | 118 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 110 BHP |
| Max. torque | 147 Nm at 4.000 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.0 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 39.2 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-27 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history****MOT #18**

2021-06-15 14:47

MOT test number

740693248250

Result**✗ Failed**

- Advice** Spare tyre defective flat cracked and perished
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #17**

2020-07-22 08:13

MOT test number

534848451840

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive gearbox leak not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16

2020-07-17 08:34

MOT test number

954814447611

Result

✗ Failed

- Advice** Oil leak, but not excessive gearbox leak not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2019-04-25 08:24

MOT test number

312275226019

Result

✓ Passed

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Auxillary belt noisy**Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced outer sill area (6.1.1 (c) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #14**

2019-04-25 08:12

MOT test number

872904787835

Result

✗ Failed

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Auxillary belt noisy**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced outer sill area (6.1.1 (c) (i))**MOT #13**

2018-05-10 07:56

MOT test number

176755490044

Result

✓ Passed

MOT #12

2018-03-10 12:17

MOT test number

987690060351

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2017-03-10 15:53**MOT test number** 165431223966**Result** ✓ Passed

Advice Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (5.2.6)

MOT #10 2017-03-10 09:51**MOT test number** 673389566087**Result** ✗ Failed

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (5.2.6)

Fail Offside Outer Seat belt anchorage prescribed area is excessively corroded sill (5.2.6)

MOT #9 2016-03-18 10:43**MOT test number** 805062672149**Result** ✓ Passed

Advice Front Outer sills corroding

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2015-04-16 14:35**MOT test number** 137686505131**Result** ✓ Passed**MOT #7** 2015-04-16 14:35**MOT test number** 725366205185**Result** ✗ Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2014-04-23 08:43**MOT test number** 815193514113**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-04-17 17:05**MOT test number** 208997703409**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-04-17 14:27**MOT test number** 629838702108**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-04-17 14:27**MOT test number** 177078402143**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2011-04-08 12:00**MOT test number** 956118291088**Result** ✓ Passed



| | |
|-----------------|---|
| MOT #1 | 2010-04-24 10:19 |
| MOT test number | 264074610404 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2007-05-30 |
| Last registration | 2021-06-15 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-05-30 | 7 mi |
| Registration #2 | 2010-04-24 | 33.920 mi |
| Registration #3 | 2011-04-08 | 37.399 mi |
| Registration #4 | 2012-04-17 | 43.330 mi |
| Registration #5 | 2013-04-17 | 50.070 mi |
| Registration #6 | 2014-04-23 | 56.342 mi |
| Registration #7 | 2015-04-16 | 63.107 mi |
| Registration #8 | 2016-03-18 | 69.940 mi |
| Registration #9 | 2017-03-10 | 83.305 mi |
| Registration #10 | 2018-03-10 | 95.377 mi |
| Registration #11 | 2019-03-10 | 107.449 mi |
| Registration #12 | 2020-03-10 | 119.521 mi |
| Registration #13 | 2021-03-10 | 131.593 mi |
| Registration #14 | 2022-03-10 | 143.665 mi |
| Registration #15 | 2023-03-10 | 155.737 mi |
| Registration #16 | 2024-03-10 | 167.809 mi |
| Registration #17 | 2025-03-10 | 179.881 mi |
| Registration #18 | 2026-03-10 | 191.953 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1667 mm |
| Height | 1521 mm |
| Length | 3850 mm |
| Wheel base | 2460 mm |
| Max. allowed weight | 1597 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 47 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FX6F3239543 |