



report date: 2024-03-29

General information

Make	VOLVO
Model	S90 D4 R-DESIGN PRO
Colour	White
Year of manufacture	2017
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	C






Internet history

Entry 4

Date	2022-01-25
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 3

Date	2022-01-25
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

Entry 2

Date	2021-10-09
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-10-09
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	16
Total items failed	0

MOT #42023-10-27 10:56

MOT test number564677823925

Result✓ Passed

Next expiry date2024-10-26

- Minor

Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Nearside Rear Nail in tyre
- Advice

Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #3** 2022-10-25 12:20**MOT test number** 318481082115**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2021-10-01 13:33**MOT test number** 861550122376**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn uneven on inner edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn uneven on inner edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2020-10-16 14:28**MOT test number** 844160266559**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-10-27
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2017-10-27	24 mi
Registration #2	2020-10-16	27.814 mi
Registration #3	2021-10-01	38.386 mi
Registration #4	2022-10-27	39.377 mi
Registration #5	2023-10-27	39.377 mi
Registration #6	2023-10-27	39.377 mi
Registration #7	2023-10-27	39.377 mi
Registration #8	2023-10-27	39.377 mi
Registration #9	2023-10-27	39.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1895 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2084394