





report date: 2024-03-29

General information

Make	BMW
Model	116 116D ED PLUS
Colour	Blue
Year of manufacture	2016
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	91.1 mpg
Consumption combined	83.1 mpg
CO2 emission	89 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date	2021-01-28
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



YK66OVV report date: 2024-03-29

MOT history

MOT expiry date	2024-07-06
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #7	2023-06-29 14:44
MOT test number	688758618045
Result	✓ Passed
Next expiry date	2024-07-06

MOT #6	2023-06-29 08:04
MOT test number	556061636077
Result	X Failed
Fail Nearside Parking brake inoperative on one side (1.4.1 (a))	
Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	

MOT #5	2022-07-02 12:14
MOT test number	430987415836
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2022-07-02 08:18

MOT test number 288753624850

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Service brake excessively fluctuating both sides (1.2.1 (e))

MOT #3 2021-07-07 14:25

MOT test number 328284709711

Result \square Passed

MOT #2 2020-09-10 12:55

MOT test number 229070177847

Result

Passed

Advice Nearside Front Tyre sidewall damaged

(e)

(e)

Advice

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2019-09-20 12:31

MOT test number 689989736915

Result
✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm tread left legal limit 1.6mm (5.2.3

Nearside Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm tread left legal limit 1.6mm (5.2.3

Advice Offside Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK SIK
Plate since	
	Moro info

CarCheck.co.uk page 8/11



YK66OVV report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



YK66OVV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-14
Last registration	2023-06-29
Complete history	See info



Registration #1	2016-09-14	27 mi
Registration #2	2019-09-20	46.474 mi
Registration #3	2020-09-10	60.853 mi
Registration #4		77,777 44
Registration #5	2021-07-07	63.130 mi
B 1 1 11 11 11 11 11 11 11 11 11 11 11 1		
Registration #6		n
Registration #6 Registration #7		1.77 46
		11.77 m

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 3	11/11

Number of axles2Engine number32479699