





report date: 2024-03-28

#### General information

Make	FIAT
Model	500C POP
Colour	White
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	Α



CarCheck.co.uk page 1/13



### Internet history


#### Entry 1


Date 2021-08-15

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-04
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	11
Total items failed	5

MOT #15	2023-10-04 13:38
MOT test number	917764309671
Result	<b>✓</b> Passed
Next expiry date	2024-10-04
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Engine cover fitted	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #14	2022-10-05 16:08
MOT test number	397629149143
Result	✓ Passed
MOT #13	2021-09-28 14:30
MOT test number	814947729317
Result	✓ Passed

CarCheck.co.uk page 3/13



Result

Fail

CK11DFO report date: 2024-03-28

× Failed

**MOT #12** 2020-10-20 12:55

MOT test number 294788393881

**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2019-05-04 07:51

**MOT test number** 348932413511

**Result** ✓ Passed

MOT #10 2019-05-03 12:13

**MOT test number** 259514502797

**Result** X Failed

Fail Offside Front Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))

MOT #9 2018-05-21 13:11

MOT test number 586962130587

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #8 2018-05-21 07:57

**MOT test number** 639261040342

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Exhaust emissions likely to be affected by an exhaust leak down pipe to centre (8.2.1.1 (b))

CarCheck.co.uk page 4/13



MOT #7 2017-06-19 13:57

**MOT test number** 941205537369

**Result** ✓ Passed

MOT #6 2017-04-06 10:29

**MOT test number** 315970550175

**Result** ✓ Passed

MOT #5 2016-04-05 14:43

**MOT test number** 271375823510

**Result** 
✓ Passed

MOT #4 2016-04-05 14:43

**MOT test number** 481967263864

**Result** X Failed

**Pass with rectification** Inner Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc both (2.5.C.1a)

MOT #3 2015-03-31 14:07

MOT test number 197520595009

**Result** ✓ Passed

MOT #2 2015-03-31 14:07

**MOT test number** 406760995035

Result × Failed

**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/13



**MOT #1** 2014-03-17 16:34

**MOT test number** 419246074007

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



#### Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	4 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



CK11DFO

report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

· ·		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report J		e?
********		
***************************************		
	More info	>
Plate changes  See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-31
Last registration	2023-10-04
Complete history	See info



Registration #1	2011-03-31	24 mi
Registration #2	2014-03-17	20.914 mi
Registration #3	2015-03-31	26.791 mi
Registration #4	2016-04-05	33.395 mi
Registration #5	2016-04-05	33.395 mi
Registration #6	2017-04-06	40.181 mi
Registration #7	2017-06-19	41.407 mi
Registration #8	2018-05-21	47.668 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/1.

Number of axles2Engine number0012511