





### General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	Blue
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I







# Internet history

Entry	2

Date Pictures 2021-09-26

35

Listing price

View report



source: autotrader.co.uk

#### Entry 1

Date	2021-09-18
Pictures	0
Listing price	View report

source: cargurus.co.uk



### MOT history

MOT expiry date	2024-10-10
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	18
Total items failed	1

MOT #12	2023-10-07 08:48
MOT test number	868203401701
Result	✓ Passed
Next expiry date	2024-10-10

MOT #11		2023-10-05 12:04
MOT test	number	213547881407
Result		🗙 Failed
Advice	Items removed from driver's view prior to test	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
<b>MAJOR</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (235 55 19 ) (5.2.3 (d) (i))		
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #10	2022-09-23 16:08
MOT test number	472097180851
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))	

МОТ #9	2021-10-11 11:25
MOT test number	138732403973
Result	✓ Passed





MOT #8	2020-10-02 10:26	
MOT test number	766938968899	
Result	✓ Passed	
MOT #7	2020-08-11 09:56	
MOT test number	678433476097	
Result	✓ Passed	
Advice Front Brake pad(s) wearing thin Both sides inner pads (1.1.13 (a) (ii))		
MOT #6	2020-08-10 14:13	
MOT test number	632609812313	
Result	🗙 Failed	
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1		
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		

Advice Front Brake pad(s) wearing thin Both sides inner pads (1.1.13 (a) (ii))

**MAJOR** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #5	2019-07-29 07:13
MOT test number	381822210988
Result	✓ Passed
MOT #4	2018-08-07 11:09
MOT test number	819156790527

Result

Passed





MOT #3		2017-08-15 09:46
MOT test	number	729898784420
Result		✓ Passed
Advice	Offside Front tyre worn on both edges	
Advice	Offside Rear tyre worn on inner edge	
Advice	Nearside Front tyre worn on both edges	
Advice	Nearside Rear tyre worn on inner edge	

MOT #2	2016-09-05 12:10
MOT test number	587368829684
Result	✓ Passed
Advice Offside Rear has a nail in centre tread causing puncture	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2016-09-05 12:1	0
MOT test number	70007254537	0
Result	× Faile	d
Advice Rear Brake pad	s) wearing thin (3.5.1g)	
Advice Offside Rear has	a nail in centre tread causing puncture	
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	



Tax & MOT check

Tax due:	✓ MOT Expires: 10 October 2024
1 October 2024 Tax status	Valid until 1 October
Days left MOT expiry date	155 10 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
	MP1E
Category	ter .
Туре	

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********		
*******		
	More info	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		

Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-30
Last registration	2023-10-07
Complete history	<u>See info</u>



Registration #1	2013-09-30	12 mi
Registration #2	2016-09-05	29.077 mi
Registration #3	2016-09-05	29.077 mi
Registration #4	2017-08-15	38.880 mi
Registration #5	2018-08-07	48.021 mi
Registration #6	2019-07-29	59.466 mi
Registration #7	2020-08-10	66.233 mi
Registration #8	2020-08-11	66.240 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi

More info  $\rightarrow$ 





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg
Additional information	
Additional information Fuel tank capacity	68 I
	68 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5