



NXIOYFV

report date: 2024-03-28

General information

Make	FORD
Model	GALAXY EDGE TDCI
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



**MOT history****MOT #12** 2022-04-05 10:38**MOT test number** 289823145217**Result** ✓ Passed**Next expiry date** 2023-04-04**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2022-04-04 13:25**MOT test number** 788810876133**Result** ✗ Failed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #10** 2021-03-10 16:22**MOT test number** 865287815455**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2021-02-27 11:30

MOT test number

444138511739

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Advice** Central exhaust heatshield insecure
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm & worn inner edge (5.2.3 (e))
- Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside fuel pipe trim insecure

MOT #8

2018-02-22 14:05

MOT test number

478204447048

Result**✓ Passed****MOT #7**

2018-02-22 12:49

MOT test number

523055958240

Result**✗ Failed**

- Fail** Offside Rear Registration plate lamp insecure (1.1.C.1c)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #6** 2017-02-23 17:10**MOT test number** 538984760635**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-03-02 13:43**MOT test number** 765366859658**Result** ✓ Passed**MOT #4** 2015-03-02 17:00**MOT test number** 697671765073**Result** ✓ Passed**MOT #3** 2015-03-02 16:56**MOT test number** 635731665071**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #2** 2014-03-03 10:58**MOT test number** 395742864033**Result** ✓ Passed**MOT #1** 2013-03-05 13:40**MOT test number** 789194463041**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-03-30
Last registration	2022-04-05
Complete history	See info



Registration #1	2010-03-30	21 mi
Registration #2	2013-03-05	76.048 mi
Registration #3	2014-03-03	110.872 mi
Registration #4	2015-03-02	131.657 mi
Registration #5	2015-03-02	131.657 mi
Registration #6	2016-03-02	153.822 mi
Registration #7	2017-02-23	175.230 mi
Registration #8	2019-03-02	201.237 mi
Registration #9	2019-03-02	201.237 mi
Registration #10	2019-03-02	201.237 mi
Registration #11	2019-03-02	201.237 mi
Registration #12	2019-03-02	201.237 mi
Registration #13	2019-03-02	201.237 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1975 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9E19303