



report date: 2024-03-29

General information

Make	FIAT
Model	STILO JTD (115 BHP) DYNAMIC
Colour	Grey
Year of manufacture	2004
Top speed	118 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	255 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





## MOT history

MOT expiry date	2021-01-02
MOT pass rate	52 %
MOT passed	12
Failed MOT tests	11
Total advice items	46
Total items failed	30

MOT #23	2019-07-03 15:13
MOT test number	754956991926
Result	✓ Passed
Next expiry date	2021-01-02

MOT #22	2019-07-02 13:15
MOT test number	622134253158
Result	✗ Failed

- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Boot lid cannot be secured in the closed position can not open (6.2.1 (e))
- MAJOR** Exhaust emissions - engine idle speed too high (8.2.1.2 (e))
- MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))
- MAJOR** Fuel cap/sealing device ineffective insecure (6.1.3 (b) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Central Rear Seat belt buckle not functioning as intended seatbelt stuck (7.1.2 (d))

**MOT #21** 2018-06-26 09:30**MOT test number** 868350588740**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #20** 2018-06-26 09:30**MOT test number** 398008753458**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #19** 2017-04-05 12:45**MOT test number** 157485470559**Result** ✓ Passed**MOT #18** 2016-04-08 11:05**MOT test number** 866027803284**Result** ✓ Passed**Advice** O/S driveshaft oil seal leaking**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #17**

2015-04-02 12:36

**MOT test number**

857902395093

**Result**

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** O/S/F brake binding slightly
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

**MOT #16**

2015-03-30 11:46

**MOT test number**

868039185019

**Result**

✗ Failed

- Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Notice** O/S/F brake binding slightly
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)

**MOT #15**

2014-03-24 11:07

**MOT test number**

498523984066

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust heatshield insecure**MOT #14**

2014-03-21 14:12

**MOT test number**

197640984077

**Result**

✗ Failed

**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Notice** Exhaust heatshield insecure**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Notice** O/S wiper starting to split, and N/S fitted incorrectly

**MOT #13**

2013-03-28 16:52

**MOT test number**

295207783058

**Result**

✓ Passed

- Notice** Both rear tyres wearing on outer edge
- Notice** Exhaust rear box corroding / clamp corroded
- Notice** Exhaust flexi blowing slightly
- Notice** O/s hadlamp adjuster running all time

**MOT #12**

2013-03-28 09:46

**MOT test number**

715397183022

**Result**

✗ Failed

- Notice** Both rear tyres wearing on outer edge
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Notice** Exhaust rear box corroding / clamp corroded
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Exhaust flexi blowing slightly
- Notice** O/s hadlamp adjuster running all time
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #11**

2012-04-11 16:20

**MOT test number**

415012502118

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #10** 2012-04-11 10:06**MOT test number** 916822402187**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2010-09-28 14:46**MOT test number** 790581470225**Result** ✓ Passed**MOT #8** 2010-09-28 09:10**MOT test number** 352411170451**Result** ✗ Failed**Fail** Offside Rear rear brake binding (3.7.B.1)**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #7** 2009-09-24 15:41**MOT test number** 131987269277**Result** ✓ Passed

**MOT #6** 2009-09-24 10:14**MOT test number** 642847669259**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2008-10-01 12:14**MOT test number** 410175278272**Result** ✓ Passed**MOT #4** 2008-10-01 09:41**MOT test number** 873755478255**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #3** 2007-09-27 10:21**MOT test number** 744760577270**Result** ✓ Passed**MOT #2** 2007-09-27 10:21**MOT test number** 614870277273**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)



MOT #1	2007-09-26 12:14
MOT test number	810579167213
Result	✗ Failed
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Advice	Nearside Front brake disc slightly pitted (3.5.1h)
Fail	Nearside front brake juddering severely (3.7.A.2b)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 January 2020

✕  
MOT

Expired:  
2 January 2021

Tax status	Expired at 1 January 2020
Days left	1581 days too late
MOT expiry date	2 January 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-09-30
Last registration	2019-07-03
Complete history	<a href="#">See info</a>



Registration #1	2004-09-30	22 mi
Registration #2	2007-09-26	25.313 mi
Registration #3	2007-09-27	25.348 mi
Registration #4	2008-10-01	33.294 mi
Registration #5	2008-10-01	33.299 mi
Registration #6	2009-09-24	41.644 mi
Registration #7	2009-09-24	41.648 mi
Registration #8	2010-09-28	49.060 mi
Registration #9	2010-09-28	49.065 mi
Registration #10	2013-03-28	11.567 mi
Registration #11	2013-03-28	11.567 mi
Registration #12	2019-07-03	25.313 mi
Registration #13	2019-07-03	25.313 mi
Registration #14	2019-07-03	25.313 mi
Registration #15	2019-07-03	25.313 mi
Registration #16	2019-07-03	25.313 mi
Registration #17	2019-07-03	25.313 mi
Registration #18	2019-07-03	25.313 mi
Registration #19	2019-07-03	25.313 mi
Registration #20	2019-07-03	25.313 mi
Registration #21	2019-07-03	25.313 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1756 mm
Height	1570 mm
Length	4516 mm
Wheel base	2600 mm
Kerb weight	1410 kg
Max. allowed weight	3220 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	3944068