





report date: 2024-03-29

### General information

Make	MINI
Model	MINI COOPER D
Colour	White
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



LX62RXY

report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-02-02

Pictures 5

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-16
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	1

MOT #12	2023-10-21 07:34
MOT test number	167570335405
Result	✓ Passed
Next expiry date	2024-11-16
Minor Offside Registration plate lamp inoperative in the case of multiple lamp (i))	os or light sources (4.7.1 (b)

MOT #11	2022-11-16 19:24
MOT test number	332693407883
Result	✓ Passed
MOT #10	2022-11-16 12:03
MOT test number	196832834822

MOT #10		2022-11-16 12:03
MOT test	number	196832834822
Result		🗙 Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4	.7.1 (b) (i))
MAJOR	Engine MIL inoperative or indicates a malfunction engine man light on (8.2.2.2 (g))	)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Front Tyre obviously under inflated (5.2.3 (I))	

CarCheck.co.uk page 3/12



LX62RXY

report date: 2024-03-29

**MOT #9** 2021-11-16 10:26

**MOT test number** 241667634524

**Result** 
✓ Passed

MOT #8 2020-11-11 10:38

**MOT test number** 732126663307

**Result** ✓ Passed

MOT #7 2020-11-05 10:02

MOT test number 510066437204

Result × Failed

**MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #6 2019-11-07 12:53

**MOT test number** 654566774176

**Result** 
✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear

bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2018-11-14 08:40

**MOT test number** 628052616642

Result \( \sqrt{Passed} \)

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



Pass with rectification

LX62RXY

report date: 2024-03-29

MOT #4	2017-11-17 11:34
MOT test number	217887674112
Result	<b>✓</b> Passed
MOT #3	2016-10-31 16:25
MOT test number	209430290173
Result	<b>✓</b> Passed
MOT #2	2015-10-24 11:49
MOT test number	104497600148
Result	<b>✓</b> Passed
MOT #1	2015-10-24 11:49
MOT test number	899285483800
Result	<b>×</b> Failed

Offside Front Tyre has ply or cords exposed sidewall cut to cord (4.1.D.1b)

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	16 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



### Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
***************************************	
********	
***************************************	
THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK AIR
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



### Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-20
Last registration	2023-10-21
Complete history	See info



Registration #1	2012-10-20	24 mi
Registration #2	2015-10-24	33.096 mi
Registration #3	2015-10-24	33.096 mi
Registration #4	2016-10-31	45.653 mi
Registration #5	2017-11-17	57.010 mi
Registration #6	2018-11-14	68.907 mi
Registration #7	2019-11-07	80.166 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



### Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 70817962