



report date: 2024-03-29

General information

|                     |                            |
|---------------------|----------------------------|
| Make                | CITROEN                    |
| Model               | XSARA HDI DESIRE 2 PICASSO |
| Colour              | Grey                       |
| Year of manufacture | -                          |
| Top speed           | 109 mph                    |
| 0 - 60 mph          | 12.6 seconds               |
| Gearbox             | 5 speed Manual             |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 90 BHP              |
| Max. torque             | 205 Nm at 1.900 rpm |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 40.4 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 51.4 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-11                  |
| Pictures      | 5                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk

**MOT history**

|                         |  |
|-------------------------|--|
| <b>MOT #28</b>          | 2024-01-25 11:49   |
| <b>MOT test number</b>  | 547433873943   |
| <b>Result</b>           | ✓ Passed   |
| <b>Next expiry date</b> | 2025-01-24   |
| <b>Advice</b>           | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| <b>Advice</b>           | N/s/f o/s/f upper strut mount bearings slightly worn                         |
| <b>Advice</b>           | Non obligatory mirror damaged  |
| <b>Advice</b>           | Gearbox mounting defective   |
| <b>Advice</b>           | Oil leak, but not excessive (8.4.1 (a) (i))                                  |
| <b>Advice</b>           | Rear axle corroded   |
| <b>Advice</b>           | Driver seat runners worn but secure  |

|                        |  |
|------------------------|--|
| <b>MOT #27</b>         | 2024-01-24 13:43   |
| <b>MOT test number</b> | 593742818591   |
| <b>Result</b>          | ✗ Failed   |
| <b>Advice</b>          | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| <b>Advice</b>          | Rear axle corroded   |
| <b>Advice</b>          | Gearbox mounting defective   |
| <b>Fail</b>            | Windscreen washer not working (3.5 (a))                                      |
| <b>Advice</b>          | Oil leak, but not excessive (8.4.1 (a) (i))                                  |
| <b>Advice</b>          | N/s/f o/s/f upper strut mount bearings slightly worn                         |
| <b>Advice</b>          | Driver seat runners worn but secure  |
| <b>Fail</b>            | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))    |
| <b>Advice</b>          | Non obligatory mirror damaged  |
| <b>Fail</b>            | Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))    |

**MOT #26** 2023-01-19 14:19**MOT test number** 213023857124**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear wiper arm missing**MOT #25** 2023-01-18 15:32**MOT test number** 758218959383**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen washer not working (3.5 (a))**Advice** Rear wiper arm missing**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Both front tyres inner edges worn**MOT #24** 2022-01-07 17:31**MOT test number** 589183411600**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Shock absorbers has a reduced damping effect both rear (5.3.2 (d))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #23**

2022-01-07 14:12

**MOT test number**

842412137246

**Result**

✗ Failed

**Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail**

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Shock absorbers has a reduced damping effect both rear (5.3.2 (d))

**Minor**

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #22**

2021-01-11 15:49

**MOT test number**

409416073264

**Result**

✓ Passed

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice**

Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice**

Play in steering rack inner joint(s)

**Advice**(e))  
Nearside Front Tyre worn close to legal limit/worn on edge on 2mm tread and bald inner (5.2.3 (e))**Advice**

Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice**

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Offside Front Coil spring corroded (5.3.1 (b) (i))



|                 |                      |
|-----------------|----------------------|
| MOT #21         | 2019-07-11 15:54     |
| MOT test number | 467960306034         |
| Result          | ✓ Passed             |
| Advice          | Spare tyre defective |

|                 |  |
|-----------------|--|
| MOT #20         | 2019-07-10 13:38   |
| MOT test number | 427345972436   |
| Result          | ✗ Failed   |
| Fail            | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))                                      |
| Advice          | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |
| Advice          | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                                   |
| Advice          | Spare tyre defective   |
| Advice          | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                                    |
| Fail            | Nearside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |
| Advice          | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |



MOT #192018-07-11 14:57

MOT test number951381546950

| Result |  | ✓ Passed |
|--------|--|----------|
| Advice | Offside Front Nail in tyre   |          |
| Advice | Offside Front Direction indicator slightly discoloured (4.4.3 (a))     |          |
| Advice | N/S AND THE O/S OUTER SILLS ARE VERY WEAK                              |          |
| Advice | Rear Tyre worn close to legal limit/worn on edge 185/65R15 (5.2.3 (e)) |          |
| Advice | CENTRE AND N/S REAR SEAT BELT CLASPS OUTER CASINGS ARE BROKEN          |          |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |          |
| Advice | Nearside Front Direction indicator slightly discoloured (4.4.3 (a))    |          |
| Advice | SMALL CHIPS IN THE WINDSCREEN  |          |
| Advice | COOLANT LEVEL IS LOW   |          |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |          |

**MOT #18**

2018-07-10 11:24

**MOT test number**

457755509861

**Result****✗ Failed****Advice** CENTRE AND N/S REAR SEAT BELT CLASPS OUTER CASINGS ARE BROKEN**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Brake hose excessively chafed (1.1.12 (b) (ii))**Advice** SMALL CHIPS IN THE WINDSCREEN**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Nail in tyre**Advice** COOLANT LEVEL IS LOW**Advice** Rear Tyre worn close to legal limit/worn on edge 185/65R15 (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Brake hose excessively chafed (1.1.12 (b) (ii))**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Advice** N/S AND THE O/S OUTER SILLS ARE VERY WEAK**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #17**

2017-07-10 15:36

**MOT test number**

501347550741

**Result****✓ Passed****Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Items removed from driver's view prior to test



**MOT #16**

2017-07-10 10:26

**MOT test number**

437989503523

**Result****✗ Failed**

- Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Items removed from driver's view prior to test

**MOT #15**

2016-07-05 14:53

**MOT test number**

838493392539

**Result****✓ Passed**

- Advice** O/s/r shockabsorber leakintg
- Advice** Rear tyres deteriorating nail in o/s/r
- Advice** Oil leak
- Advice** N/s/r shockabsorber dust cover deteriorating
- Advice** N/s/f tyre getting low
- Advice** Wiper blades starting to smear screen

**MOT #14**

2016-07-05 14:53

**MOT test number**

354103129459

**Result****✗ Failed****Advice** Oil leak**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** N/s/r shockabsorber dust cover deteriorating**Advice** N/s/f tyre getting low**Advice** Wiper blades starting to smear screen**Advice** O/s/r shockabsorber leakintg**Pass with rectification** Offside Front position lamp(s) not working side light (1.1.A.3b)**Advice** Rear tyres deteriorating nail in o/s/r**MOT #13**

2015-07-03 15:57

**MOT test number**

336464085102

**Result****✓ Passed****Notice** N/s/f tyre showing signs of wearing pon inner edge**Notice** Rear tyres starting to deteriate**Notice** Front brake pads appear to be getting low**Notice** Rear shockabsorbers dust covers deteriorating**Notice** Nail in o/s/r tyre

**MOT #12**

2014-07-11 16:32

**MOT test number**

268492594168

**Result**

✓ Passed

**Notice** Slight binding to o/s/r wheel when rotated**Notice** Wiper blades split**Notice** Noise when rotating front wheels**Notice** Front tyres wearing on edges**MOT #11**

2014-06-28 12:15

**MOT test number**

166849774125

**Result**

✗ Failed

**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Front tyres wearing on edges**Notice** Slight binding to o/s/r wheel when rotated**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Wiper blades split**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Notice** Noise when rotating front wheels**MOT #10**

2013-05-20 09:08

**MOT test number**

867820943195

**Result**

✓ Passed

**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay



|                 |   |
|-----------------|---|
| MOT #9          | 2012-05-21 16:00                                    |
| MOT test number | 167302142145  |
| Result          | ✓ Passed  |
| Notice          | N/s/r seat belt partialy tested / child seat fitted |

|                         |  |
|-------------------------|--|
| MOT #8                  | 2012-05-21 11:05   |
| MOT test number         | 958102442104   |
| Result                  | ✗ Failed   |
| Pass with rectification | Offside Side repeater incorrect colour (1.4.A.2f)              |
| Notice                  | N/s/r seat belt partialy tested / child seat fitted            |
| Notice                  | Nail in o/s/r tyre   |
| Pass with rectification | Nearside Headlamp aim too low (1.8)                            |
| Pass with rectification | Nearside Rear Direction indicators incorrect colour (1.4.A.2f) |
| Pass with rectification | Nearside Side repeater incorrect colour (1.4.A.2f)             |
| Fail                    | Rear Exhaust system not adequately supported (7.1.1)           |
| Notice                  | O/s wiper blade split at end / starting to smear screen        |
| Pass with rectification | Offside Headlamp aim too low (1.8)                             |
| Pass with rectification | Offside Rear Direction indicators incorrect colour (1.4.A.2f)  |



MOT #7

2011-05-16 09:17

MOT test number

619556231127

Result

✓ Passed

- Notice

Child seat fitted not allowing full inspection of adult belt
- Notice

Offside front wiper blade slightly smearing screen
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Nearside front wiper blade slightly smearing screen
- Notice

Offside rear tyre perished
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

2011-05-16 09:17

MOT test number

785766531103

Result

✗ Failed

- Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Nearside front wiper blade slightly smearing screen
- Notice

Offside rear tyre perished
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Child seat fitted not allowing full inspection of adult belt
- Notice

Offside front wiper blade slightly smearing screen

**MOT #5** 2010-05-06 09:28**MOT test number** 220706120477**Result** ✓ Passed

- Notice** Engine top cover insecure
- Notice** Rear wiper blade split
- Notice** O/S door mirror cover missing

**MOT #4** 2009-05-11 11:39**MOT test number** 253031439493**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Notice** Rear wiper blade
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #3** 2009-05-11 11:39**MOT test number** 242811539108**Result** ✓ Passed

- Notice** Rear wiper blade
- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #2** 2008-06-05 15:24**MOT test number** 894097958159**Result** ✓ Passed



|                 |                  |
|-----------------|------------------|
| MOT #1          | 2007-10-25 16:10 |
| MOT test number | 284108297296     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 0          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 28                       |
| First mileage registration | 2004-09-30               |
| Last registration          | 2024-01-25               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2004-09-30 | 15 mi      |
| Registration #2  | 2007-10-25 | 52.789 mi  |
| Registration #3  | 2008-06-05 | 54.924 mi  |
| Registration #4  | 2009-05-11 | 61.459 mi  |
| Registration #5  | 2010-05-06 | 69.339 mi  |
| Registration #6  | 2011-05-16 | 80.795 mi  |
| Registration #7  | 2012-05-21 | 94.524 mi  |
| Registration #8  | 2012-05-21 | 94.524 mi  |
| Registration #9  | 2013-05-20 | 107.626 mi |
| Registration #10 | 2014-06-28 | 117.752 mi |
| Registration #11 | 2014-07-11 | 117.752 mi |
| Registration #12 | 2015-07-03 | 126.505 mi |
| Registration #13 | 2016-07-05 | 134.534 mi |
| Registration #14 | 2016-07-05 | 134.534 mi |
| Registration #15 | 2016-07-05 | 134.534 mi |
| Registration #16 | 2016-07-05 | 134.534 mi |
| Registration #17 | 2016-07-05 | 134.534 mi |
| Registration #18 | 2016-07-05 | 134.534 mi |
| Registration #19 | 2016-07-05 | 134.534 mi |
| Registration #20 | 2016-07-05 | 134.534 mi |
| Registration #21 | 2016-07-05 | 134.534 mi |
| Registration #22 | 2016-07-05 | 134.534 mi |
| Registration #23 | 2016-07-05 | 134.534 mi |
| Registration #24 | 2016-07-05 | 134.534 mi |
| Registration #25 | 2016-07-05 | 134.534 mi |
| Registration #26 | 2016-07-05 | 134.534 mi |

|                  |            |            |
|------------------|------------|------------|
| Registration #27 | 2025-25-25 | 25,252,452 |
| Registration #28 | 2025-25-25 | 25,252,452 |

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 1751 mm |
| Height      | 1637 mm |
| Length      | 4276 mm |
| Wheel base  | 2760 mm |
| Kerb weight | 1300 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Engine number      | DYRZ4017511      |