





report date: 2024-03-28

General information

Make	MAZDA
Model	6 TS
Colour	Black
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	165 Nm at 4.300 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-28

MOT history

MOT expiry date	2021-03-18
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	6
Total items failed	8

MOT #13	2020-03-10 11:07
MOT test number	789316486046
Result	✓ Passed
Next expiry date	2021-03-18

MOT #12	20	20-03-09 11:45
MOT test	number	985139428728
Result		X Failed
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b	o) (ii))
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2	(b))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Headlamp aim too low both (4.1.2 (a))	

MOT #11	2019-03-14 11:03
MOT test number	567771045303
Result	✓ Passed
MOT #10	2018-03-15 11:19
MOT test number	325825504578
Result	✓ Passed

CarCheck.co.uk page 2/11



Result

SH08NZX

report date: 2024-03-28

✓ Passed

MOT #9	2017-03-16 17:30
MOT test number	769373938283
Result	✓ Passed
MOT #8	2017-03-15 13:22
MOT test number	810978148659
Result	× Failed
Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Headlamp aim too low (1.8)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Fail Nearside Rear brake caliper leaking (3.6.A.1)	
Fail Exhaust emissions carbon monoxide content at idle excessive (7.3	3.D.4)
Fail Nearside Headlamp aim too low (1.8)	

MOT #7	2016-03-10 15:35
MOT test number	100201108564
Result	✓ Passed
MOT #6	2015-03-13 12:13
MOT test number	175852175054
Result	✓ Passed
MOT #5	2014-03-15 15:09
MOT test number	758444274076

CarCheck.co.uk page 3/11



report date: 2024-03-28

 MOT #4
 2013-03-19 13:36

 MOT test number
 665818273013

 Result
 ✓ Passed

 MOT #3
 2012-07-07 10:53

 MOT test number
 666759782169

 Result
 ✓ Passed

 Notice
 Front wipers worn

MOT #2

MOT test number

Result

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

Notice

Front wipers worn

MOT #1	2011-06-03 15:19
MOT test number	835354151171
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check

Tax expired: 25 January 2021



Expired: 18 March 2021 X MOT

Tax status	Expired at 25 January 2021
Days left	1190 days too late
MOT expiry date	18 March 2021
Full MOT history	See MOT history

Tax calculation

Waltisla alasa	40
Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

SH08NZX

report date: 2024-03-28

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-06-26
Last registration	2020-03-10
Complete history	See info



Registration #1	2008-06-26	26 mi
Registration #2	2011-06-03	34.611 mi
Registration #3	2012-07-07	46.526 mi
Registration #4	2013-03-19	50.790 mi
Registration #5	2014-03-15	56.362 mi
Registration #6	2015-03-13	66.236 mi
Registration #7	2016-03-10	74.493 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 ms
Registration #12		0.00 44
Registration #13		11.777 no

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L8 20244999

CarCheck.co.uk page 11/11