



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	White
Year of manufacture	2013
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	16
Total items failed	15

MOT #14	2024-03-18 14:28
MOT test number	710920948765
Result	✓ Passed
Next expiry date	2025-03-29
Advice	Offside Front Upper Shock absorbers has a slightly worn bush shocker bearing slightly seized (5.3.2 (c))

MOT #13	2024-03-18 11:22
MOT test number	478708358073
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Advice	Offside Front Upper Shock absorbers has a slightly worn bush shocker bearing slightly seized (5.3.2 (c))
Fail	Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

MOT #12	2023-03-14 10:34
MOT test number	996710153696
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge nearside and offside (5.2.3 (e))

**MOT #11** 2023-03-14 09:33**MOT test number** 185908440755**Result** ✗ Failed**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge nearside and offside (5.2.3 (e))**MOT #10** 2022-03-15 12:00**MOT test number** 263544217884**Result** ✓ Passed**MOT #9** 2021-03-30 14:17**MOT test number** 982485124049**Result** ✓ Passed**MOT #8** 2021-03-30 08:53**MOT test number** 727026860497**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #7** 2019-12-09 11:41**MOT test number** 385824809649**Result** ✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #6 2019-01-03 16:37**MOT test number** 616838812096**Result** ✓ Passed**MOT #5** 2019-01-03 10:32**MOT test number** 891371027800**Result** ✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #4 2017-07-18 12:37**MOT test number** 209404715527**Result** ✓ Passed



MOT #3	2017-07-15 08:41
MOT test number	585373753754
Result	✗ Failed
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)
Fail	Parking brake: efficiency below requirements (3.7.B.7)

MOT #2	2016-07-25 10:34
MOT test number	634055364044
Result	✓ Passed

MOT #1	2016-07-25 09:56
MOT test number	823180415530
Result	✗ Failed
Fail	Offside Rear fog lamp emits a light other than red (1.3.2e)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 March 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-07-26
Last registration	2024-03-18
Complete history	See info



Registration #1	2013-07-26	16 mi
Registration #2	2016-07-25	27.333 mi
Registration #3	2016-07-25	27.333 mi
Registration #4	2017-07-15	36.344 mi
Registration #5	2017-07-18	36.348 mi
Registration #6	2019-01-03	43.315 mi
Registration #7	2019-01-03	43.315 mi
Registration #8	2019-12-09	52.099 mi
Registration #9	2020-03-20	55.277 mi
Registration #10	2020-03-20	55.277 mi
Registration #11	2020-03-20	55.277 mi
Registration #12	2020-03-20	55.277 mi
Registration #13	2020-03-20	55.277 mi
Registration #14	2020-03-20	55.277 mi
Registration #15	2020-03-20	55.277 mi
Registration #16	2020-03-20	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	0450628