



BWIIAAJ

report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 LWB P/V HDI 120 LX
Colour	White
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-07
Pictures	0
Listing price	View report

source: cargurus.co.uk

**MOT history**

MOT #11	2021-10-19 16:12
MOT test number	321594371072
Result	✓ Passed
Next expiry date	2022-10-18
Minor	Windscreen wiper blade defective both (3.4 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view 2 cracks (3.2 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-09-28 16:42
MOT test number	928823987055
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view 2 cracks (3.2 (a) (i))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Windscreen wiper blade defective both (3.4 (b) (i))

**MOT #9** 2020-09-29 11:17**MOT test number** 831820637217**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-10-04 14:52**MOT test number** 245619310045**Result** ✓ Passed**MOT #7** 2018-09-26 15:19**MOT test number** 956511779983**Result** ✓ Passed**MOT #6** 2018-09-26 15:19**MOT test number** 359103620874**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a))**MOT #5** 2017-09-01 16:47**MOT test number** 802850886753**Result** ✓ Passed

**MOT #4**

2017-08-25 12:34

MOT test number

919966551269

Result

✗ Failed

Fail

Nearside Headlamp aim too high and too far to the right. (1.8)

Fail

Offside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)

Fail

Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice

G/box mounting torn

MOT #3

2016-08-13 09:04

MOT test number

880106562361

Result

✓ Passed

Advice

Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Advice

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice

Rear Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

Advice

Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Advice

Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #2

2015-09-01 14:32

MOT test number

952292094215

Result

✓ Passed

MOT #1

2014-08-06 08:42

MOT test number

859818914243

Result

✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-08-17
Last registration	2021-10-19
Complete history	See info



Registration #1	2011-08-17	18 mi
Registration #2	2014-08-06	68.265 mi
Registration #3	2015-09-01	101.759 mi
Registration #4	2016-08-13	126.005 mi
Registration #5	2017-08-25	222.377 mi
Registration #6	2017-09-01	138.393 mi
Registration #7	2018-09-26	144.648 mi
Registration #8	2019-09-26	151.377 mi
Registration #9	2019-09-26	151.377 mi
Registration #10	2019-09-26	151.377 mi
Registration #11	2019-09-26	151.377 mi
Registration #12	2019-09-26	151.377 mi
Registration #13	2019-09-26	151.377 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1894 mm
Length	5135 mm
Kerb weight	1680 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	DYXA4051041