



FL57WSY


report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	2007
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-08
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	13
Total items failed	8

MOT #22	2023-10-13 10:32
MOT test number	396272070828
Result	✓ Passed
Next expiry date	2024-10-15
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Exhaust middle box outer sleeve insecure
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #21	2022-10-14 15:44
MOT test number	560479902631
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing tyre over (10 years old) (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tyre over (10years old) (5.2.3 (d) (ii))

**MOT #20** 2022-10-14 14:28**MOT test number** 783168180567**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre over (10 years old) (5.2.3 (d) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre over (10years old) (5.2.3 (d) (ii))**MOT #19** 2021-10-16 09:58**MOT test number** 864966163793**Result** ✓ Passed**MOT #18** 2021-07-01 08:54**MOT test number** 519295379613**Result** ✓ Passed**MOT #17** 2020-07-13 13:47**MOT test number** 364271010116**Result** ✓ Passed**MOT #16** 2019-07-09 08:19**MOT test number** 812405146595**Result** ✓ Passed**MOT #15** 2019-07-08 12:25**MOT test number** 389534939696**Result** ✗ Failed**Fail** Offside Headlamp aim too high (4.1.2 (a))

**MOT #14** 2018-07-13 08:43**MOT test number** 113462594519**Result** ✓ Passed**MOT #13** 2017-07-18 09:58**MOT test number** 204939375796**Result** ✓ Passed**Advice** Steering system slightly tight (2.2.D.1)**MOT #12** 2017-07-17 09:54**MOT test number** 348312124325**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Steering system slightly tight (2.2.D.1)**Fail** Main beam 'tell-tale' not working (1.7.4c)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #11** 2016-07-26 14:25**MOT test number** 711324951968**Result** ✓ Passed**Advice** Tread depths; both front 5.0mm, both rear 6.0mm, spare 7.5mm, 185/65/15 88h**MOT #10** 2015-08-03 13:06**MOT test number** 332425504583**Result** ✓ Passed**Advice** Tread depths: both front on 5mm, n/s/r on 5.5mm, o/s/r on 6mm.**Advice** Tyre size: 185/65/15 88H.

**MOT #9** 2015-08-03 08:45**MOT test number** 116632360918**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2014-07-25 10:35**MOT test number** 245596704219**Result** ✓ Passed**MOT #7** 2014-06-23 14:56**MOT test number** 836684574124**Result** ✓ Passed**MOT #6** 2013-07-11 17:30**MOT test number** 917422393194**Result** ✓ Passed**MOT #5** 2012-07-20 13:10**MOT test number** 415442102214**Result** ✓ Passed**MOT #4** 2012-07-16 12:04**MOT test number** 586178092107**Result** ✗ Failed**Fail** Power steering component(s) leaking from a failed seal (2.3.3b)**MOT #3** 2011-08-08 09:37**MOT test number** 717510121292**Result** ✓ Passed



MOT #2	2010-08-09 12:00
MOT test number	863991820204
Result	✓ Passed

MOT #1	2010-08-09 10:18
MOT test number	311491320480
Result	✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	FL57WSY
Plate since	2024-03-29
Current registration	FL57WSY
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-09-13
Last registration	2023-10-13
Complete history	See info



Registration #1	2007-09-13	20 mi
Registration #2	2010-08-09	9.528 mi
Registration #3	2010-08-09	9.530 mi
Registration #4	2011-08-08	14.189 mi
Registration #5	2012-07-16	18.850 mi
Registration #6	2012-07-20	18.850 mi
Registration #7	2013-07-11	22.691 mi
Registration #8	2014-06-23	27.832 mi
Registration #9	2014-07-25	28.914 mi
Registration #10	2015-08-03	31.613 mi
Registration #11	2015-08-03	31.613 mi
Registration #12	2016-07-26	33.315 mi
Registration #13	2016-07-26	33.315 mi
Registration #14	2016-07-26	33.315 mi
Registration #15	2016-07-26	33.315 mi
Registration #16	2016-07-26	33.315 mi
Registration #17	2016-07-26	33.315 mi
Registration #18	2016-07-26	33.315 mi
Registration #19	2016-07-26	33.315 mi
Registration #20	2016-07-26	33.315 mi
Registration #21	2016-07-26	33.315 mi
Registration #22	2016-07-26	33.315 mi
Registration #23	2016-07-26	33.315 mi
Registration #24	2016-07-26	33.315 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3258333