




report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	420 BHP
Max. torque	560 Nm at 4.000 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.8 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	294 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-07-28
Pictures	50
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-22
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	6
Total items failed	8

MOT #18	2023-12-23 16:03
MOT test number	336003007893
Result	✓ Passed
Next expiry date	2024-12-22

MOT #17	2022-10-19 09:21
MOT test number	908994747353
Result	✓ Passed

MOT #16	2021-10-21 14:13
MOT test number	921616865554
Result	✓ Passed

MOT #15	2020-09-23 11:18
MOT test number	685312879625
Result	✓ Passed

MOT #14	2019-09-27 08:03
MOT test number	277876692466
Result	✓ Passed

**MOT #13** 2018-09-21 14:21**MOT test number** 942880103836**Result** ✓ Passed**MOT #12** 2018-04-05 07:26**MOT test number** 464161372046**Result** ✓ Passed**MOT #11** 2017-04-10 10:33**MOT test number** 517862900150**Result** ✓ Passed**MOT #10** 2017-04-05 09:01**MOT test number** 784620390447**Result** ✗ Failed

Fail Nearside Rear Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Rear Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Rear Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #9 2016-04-06 16:37**MOT test number** 462281741333**Result** ✓ Passed

Advice Nearside Rear Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #8** 2016-04-04 11:37**MOT test number** 891889199039**Result** ✗ Failed

Advice Offside Rear Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Offside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Rear Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Nearside Rear Outer Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Rear Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Nearside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #7 2015-03-24 09:56**MOT test number** 225603585046**Result** ✓ Passed**MOT #6** 2014-03-29 10:17**MOT test number** 795398284083**Result** ✓ Passed**MOT #5** 2014-03-26 14:46**MOT test number** 748705584019**Result** ✗ Failed

Fail Nearside Front Headlamp aim too low (1.8)

MOT #4 2013-03-19 09:42**MOT test number** 255938973030**Result** ✓ Passed



MOT #3	2012-03-08 14:05
MOT test number	547328762053
Result	✓ Passed

MOT #2	2011-03-11 09:49
MOT test number	337240971053
Result	✓ Passed
<div><div>Advice</div>Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	
<div><div>Advice</div>Nearside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	

MOT #1	2010-03-10 13:49
MOT test number	332319060061
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
22 December 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	JC07XKR
Plate since	2019-03-29
Current registration	JC07XKR
Plate since	2019-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



report date: 2024-03-29

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-04-04
Last registration	2023-12-23
Complete history	See info



Registration #1	2007-04-04	23 mi
Registration #2	2010-03-10	12.957 mi
Registration #3	2011-03-11	15.768 mi
Registration #4	2012-03-08	18.236 mi
Registration #5	2013-03-19	19.911 mi
Registration #6	2014-03-26	21.540 mi
Registration #7	2014-03-29	21.540 mi
Registration #8	2015-03-24	23.516 mi
Registration #9	2016-04-04	24.735 mi
Registration #10	2016-04-06	24.735 mi
Registration #11	2016-05-20	25.277 mi
Registration #12	2016-05-20	25.277 mi
Registration #13	2016-05-20	25.277 mi
Registration #14	2016-05-20	25.277 mi
Registration #15	2016-05-20	25.277 mi
Registration #16	2016-05-20	25.277 mi
Registration #17	2016-05-20	25.277 mi
Registration #18	2016-05-20	25.277 mi
Registration #19	2016-05-20	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1715 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	07020117059G