



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T2
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-12
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-04-12
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	26
Total items failed	9

MOT #16	2022-04-13 11:50
MOT test number	824306582105
Result	✓ Passed
Next expiry date	2023-04-12
<b>Minor</b>	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15	2021-01-05 13:03
MOT test number	779946620455
Result	✓ Passed
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Minor</b>	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #14**

2021-01-05 13:03

**MOT test number**

617339777743

**Result****✗ Failed****Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Pass with rectification** Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #13**

2019-05-07 08:21

**MOT test number**

879407435560

**Result****✓ Passed****Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing badly feathering,advise alignment check asap (5.2.3 (d) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/5516 slick on inner edge (5.2.3 (e))**MOT #12**

2019-05-07 08:21

**MOT test number**

704417291719

**Result****✗ Failed****Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing badly feathering,advise alignment check asap (5.2.3 (d) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/5516 slick on inner edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #11**

2018-05-10 10:27

**MOT test number**

921612675850

**Result**

✓ Passed

- Advice** Rear Bumper insecure
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit slick on edges but no cords visible at time of test 205/5516 (4.1.E.1)

**MOT #10**

2018-05-10 08:34

**MOT test number**

581678716634

**Result**

✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit slick on edges but no cords visible at time of test 205/5516 (4.1.E.1)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Rear Bumper insecure

**MOT #9**

2017-05-10 11:39

**MOT test number**

814455858237

**Result**

✓ Passed

**MOT #8** 2017-05-10 11:39**MOT test number** 262767625610**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #7** 2016-05-09 12:04**MOT test number** 429771405661**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test

**MOT #6** 2016-05-09 12:04**MOT test number** 625960632373**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Advice** Items removed from driver's view prior to test

**MOT #5** 2015-05-21 15:42**MOT test number** 886681445150**Result** ✓ Passed**MOT #4** 2014-05-22 16:48**MOT test number** 675252444100**Result** ✓ Passed**MOT #3** 2013-03-04 11:02**MOT test number** 958013363091**Result** ✓ Passed



MOT #2	2012-02-16 15:45
MOT test number	176137742013
Result	✓ Passed

MOT #1	2012-02-16 10:55
MOT test number	518637442093
Result	✗ Failed

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:  
31 July 2022

X

MOT

Expired:  
12 April 2023

Tax status	Expired at 31 July 2022
Days left	637 days too late
MOT expiry date	12 April 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	RE08XAJ
Plate since	2024-03-29
Current registration	RE08XAJ
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-16
Last registration	2022-04-13
Complete history	<a href="#">See info</a>



Registration #1	2008-04-16	12 mi
Registration #2	2012-02-16	41.388 mi
Registration #3	2012-02-16	41.390 mi
Registration #4	2013-03-04	52.759 mi
Registration #5	2014-05-22	61.982 mi
Registration #6	2015-05-21	70.738 mi
Registration #7	2016-05-09	88.486 mi
Registration #8	2016-05-09	88.486 mi
Registration #9	2017-05-10	104.215 mi
Registration #10	2018-05-10	120.000 mi
Registration #11	2019-05-10	135.000 mi
Registration #12	2020-05-10	150.000 mi
Registration #13	2021-05-10	165.000 mi
Registration #14	2022-05-10	180.000 mi
Registration #15	2023-05-10	195.000 mi
Registration #16	2024-05-10	210.000 mi
Registration #17	2025-05-10	225.000 mi
Registration #18	2026-05-10	240.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	2AD5363409