



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI SE
Colour	Silver
Year of manufacture	2017
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-22
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-20
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	10
Total items failed	16

MOT #9 2024-01-20 10:31

MOT test number 724188722711

Result ✓ Passed

Next expiry date 2025-01-20

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2024-01-20 10:31

MOT test number 339428307935

Result ✗ Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2023-01-05 16:38

MOT test number 642879170033

Result ✓ Passed

**MOT #6** 2022-01-21 16:04**MOT test number** 852181965241**Result** ✓ Passed**MOT #5** 2022-01-20 12:22**MOT test number** 120581492842**Result** ✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Fluid leak harmful to the environment or a risk to other road users FUEL FILTER LEAKING (8.4.1 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4 2021-06-07 14:11**MOT test number** 545837620381**Result** ✓ Passed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #3** 2021-06-07 09:55**MOT test number** 207623851943**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #2** 2020-05-27 09:23**MOT test number** 849575915634**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))**MOT #1** 2020-05-27 09:23**MOT test number** 582141400647**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
First licence fee (12 months)	£ 1.565,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 2.220,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EF17UDN
Plate since	2024-03-29
Current registration	EF17UDN
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-06-05
Last registration	2024-01-20
Complete history	See info



Registration #1	2017-06-05	29 mi
Registration #2	2020-05-27	56.256 mi
Registration #3	2020-05-27	56.256 mi
Registration #4	2021-06-07	71.735 mi
Registration #5	2021-06-07	71.735 mi
Registration #6	2022-05-27	85.277 mi
Registration #7	2022-05-27	85.277 mi
Registration #8	2023-05-27	98.277 mi
Registration #9	2023-05-27	98.277 mi
Registration #10	2023-05-27	98.277 mi
Registration #11	2024-01-20	111.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2248 kg
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBG180998