




report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Grey
Year of manufacture	2009
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-11-05
Pictures	29
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-10-26
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #16	2023-10-23 10:11
MOT test number	398613063122
Result	✓ Passed
Next expiry date	2024-10-26
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-10-27 11:45
MOT test number	961798693031
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2022-10-25 15:00

MOT test number

877047411630

Result**✗ Failed**

Advice Nearside Front Tyre slightly damaged/cracking or perishing Tread has age perished cracking. It is the opinion of the Tester that this tyre should be replaced soon. (5.2.3 (d) (ii))

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tread has age perished cracking. It is the opinion of the Tester that this tyre should be replaced soon. (5.2.3 (d) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing Tread has age perished cracking. It is the opinion of the Tester that this tyre should be replaced soon. (5.2.3 (d) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Inner clamp not secure. (6.1.7 (g) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Tread has age perished cracking. It is the opinion of the Tester that this tyre should be replaced soon. (5.2.3 (d) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2021-06-28 10:53

MOT test number

112817217064

Result**✓ Passed**

Advice All tyres tread good (cracking between treads)

MOT #12

2021-06-28 10:53

MOT test number

844310043555

Result**✗ Failed**

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice All tyres tread good (cracking between treads)

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11

2020-07-06 11:48

MOT test number

760214085784

Result**✓ Passed**
page 4/13

**MOT #10** 2020-07-06 11:48**MOT test number** 634187669174**Result** ✗ Failed**Pass with rectification** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2019-06-11 13:08**MOT test number** 468479028411**Result** ✓ Passed**MOT #8** 2018-06-01 13:33**MOT test number** 879790915638**Result** ✓ Passed**MOT #7** 2017-05-31 09:57**MOT test number** 766612574253**Result** ✓ Passed**MOT #6** 2016-06-01 09:41**MOT test number** 956124868366**Result** ✓ Passed**MOT #5** 2015-06-08 11:22**MOT test number** 195489555173**Result** ✓ Passed**MOT #4** 2015-06-08 11:22**MOT test number** 188629155142**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #3	2014-06-04 12:52
MOT test number	417785754156
Result	✓ Passed
MOT #2	2013-06-20 13:11
MOT test number	246931973497
Result	✓ Passed
MOT #1	2012-06-15 12:50
MOT test number	905017262183
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EJ09KBN
Plate since	2019-03-28
Current registration	EJ09KBN
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-17
Last registration	2023-10-23
Complete history	See info



Registration #1	2009-06-17	18 mi
Registration #2	2012-06-15	6.422 mi
Registration #3	2013-06-20	7.374 mi
Registration #4	2014-06-04	9.693 mi
Registration #5	2015-06-08	10.329 mi
Registration #6	2016-06-01	11.361 mi
Registration #7	2017-05-31	12.716 mi
Registration #8	2018-06-01	13.629 mi
Registration #9	2019-06-11	14.403 mi
Registration #10	2020-06-01	15.216 mi
Registration #11	2021-06-01	16.029 mi
Registration #12	2022-06-01	16.842 mi
Registration #13	2023-06-01	17.655 mi
Registration #14	2024-03-28	18.468 mi
Registration #15		
Registration #16		
Registration #17		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9B68595