



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 VTR
Colour	Silver
Year of manufacture	2009
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-23
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-11
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	30
Total items failed	11

MOT #19 2024-03-19 19:02

MOT test number 743655679154

Result ✓ Passed

Next expiry date 2025-04-11

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Coil spring corroded both (5.3.1 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #18 2023-04-12 15:48

MOT test number 932632265859

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2023-04-03 14:48

MOT test number

810697967133

Result**✗ Failed**

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Horn not working (7.7 (a))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16

2022-02-09 08:37

MOT test number

855279445643

Result**✓ Passed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15

2022-01-31 11:11

MOT test number

561487180260

Result**✗ Failed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))

MOT #14

2021-01-13 16:20

MOT test number

862227425899

Result**✓ Passed**

**MOT #13** 2020-10-02 09:30**MOT test number** 271317188194**Result** ✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

MOT #12 2020-09-24 12:34**MOT test number** 368459112843**Result** ✗ Failed

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Fail Offside Rear Lower Coil spring mounting damaged and seriously weakened missing (5.3.1 (b) (i))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11 2019-09-19 10:22**MOT test number** 157385023222**Result** ✓ Passed

Advice Exhaust back box bracket broken but exhaust still secure

Minor Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #10 2018-09-29 07:54**MOT test number** 950827399600**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides, (1.1.14 (a) (ii))

Advice Steering column top bearing slightly worn (2.2.2 (b))

Advice Rear exhaust has a temporary repair.

**MOT #9** 2018-09-29 07:54**MOT test number** 822990556169**Result** ✗ Failed**Advice** Rear exhaust has a temporary repair.**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both sides, (3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides, (1.1.14 (a) (ii))**Advice** Steering column top bearing slightly worn (2.2.2 (b))**MOT #8** 2016-05-10 09:52**MOT test number** 494826887011**Result** ✓ Passed**MOT #7** 2015-04-21 14:05**MOT test number** 125381715195**Result** ✓ Passed**Notice** Backbox exhaust slightly deteriorated**MOT #6** 2014-03-12 12:34**MOT test number** 975151874087**Result** ✓ Passed**MOT #5** 2014-01-25 12:44**MOT test number** 506525824074**Result** ✓ Passed**Notice** ADVISE, both front wiper blades split at ends.**Notice** ADVISE, slight oil leak.

**MOT #4** 2014-01-25 09:45**MOT test number** 445025924012**Result** ✗ Failed**Fail** Horn not loud enough to be heard by another road user (1.6.2b)**Notice** ADVISE, both front wiper blades split at ends.**Notice** ADVISE, slight oil leak.**MOT #3** 2013-02-27 15:48**MOT test number** 667678553014**Result** ✓ Passed**MOT #2** 2013-02-27 09:28**MOT test number** 909548453029**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #1** 2012-02-09 11:57**MOT test number** 229070342047**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-31
Last registration	2024-03-19
Complete history	See info



Registration #1	2009-01-31	18 mi
Registration #2	2012-02-09	18.731 mi
Registration #3	2013-02-27	16.900 mi
Registration #4	2013-02-27	30.597 mi
Registration #5	2014-01-25	40.213 mi
Registration #6	2014-01-25	40.213 mi
Registration #7	2014-03-12	40.393 mi
Registration #8	2015-04-21	51.429 mi
Registration #9	2016-05-10	52.517 mi
Registration #10	2018-09-29	53.864 mi
Registration #11	2018-09-29	53.864 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi
Registration #20	2019-05-20	55.277 mi
Registration #21	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	990 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST36122073